## LAND CORNER RECORDATION CERTIFICATE Fiting Requirement of Act 74, Mich. P.A. 1970

For corners in		, Tilling frequirement of Act (4) thiot.	
-	IFOS (County)	Located In:	Corner Code ≠#
1.	Public Land Survey	T 43N R 32N T 43N R 32N T 43N R 32N	D6 E7 C7
2.	Property Controlling in Section	S T R S T R	

Register of Deeds Stamp & File Number

4. Lot No \_\_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_\_

3. Miscellaneous

Property in Sec.

C7 June 08, 1994 E7 June 08, 1994

I. \$tephan J. \$tystlosk1 \_\_\_\_\_\_, in a field survey on \$\overline{0}\$\_ \$\begin{array}{ll} \text{lay} & \text{...} & \text{.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A Description of original monument and accessories and/or subsequent restoration:

(96) Center of Section 17. Corner not established in the original survey. Found no subsequent record.

(E7) Corner common to Sections 16-17-20-21. Corner established in 1849 by Z.B. Searles as follows: Set cedar post, Tamarack 12 S41W 30, Tamarack 10 N74E 47. Found no subsequent record.

(C7) Corner common to sections 17-18-19-20. Corner estabalished in 1849 by Z.B. Searles as follows: Set maple post, W. Birch 16 S40W 21, Cedar 10 N24E 29. Original record show distances to adjacent corners: 40.00 north, 80.09 west, 80.00 east, 40.00 south. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

[D6] Found no monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite quarter corners, all monumented. At the position for the corner, I placed a 1"I.D.x32" iron pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped.

(E7) Original post and accessories not recovered. Found a 5° dial concrete filled stove pipe with a drill rod in the center, projecting 18°, in a tag alder swamp. Recovered new bearing trees marked with upper and lower blazes and measuring nails in their sides recently established by unknown surveyor. This monument was probably placed long ago by mining company surveyors. No record of their work was found. Corner checks acceptably with monumented corners to the north and mest. Accepted the monument as the best available evidence of the position of the original corner.

(CT) Original post and accessories not recovered. Found a 17 dia, solid iron bar, previously mitnessed by unknown surveyor, with several old blazes facing it. Position of the bar checks fairly well with the original record to monumented corners as follows, 40.045 north, 79.997 mest, 40.0 south (from recorded survey by others), and 79.394 east. Accepted the bar as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

[E7] Found 5' stove
Blazed and scribed the following bearing
trees:
6' Cedar S19W 3.0' 1/4S BT 12' Tanarack N42N 16
20' R. Pine N89W 28.7' 1/4S BT 5' Balsam S65E 34.7'
20' R. Pine N64W 39.4' 1/4S BT 5' Balsam N74E 55.3'
20' R. Pine N67E 85.4' 1/4S BT 5' Balsam N74E 55.3'
20' R. Pine N67E 85.4' 1/4S BT 5' Balsam N74E 55.3'
Corner falls 40' west of center of N83E 27.85'
Rockcrusher road. Bearings are
magnetic.

Surveyor's Michigan License No.

[E7] Found 5' stove pipe, conc. filled with drill rod in center, projecting 18'. Measured to the existing NBTs: 12' Tamarack N42W 100.1' 5' Balsam 568E 34.7' 5' Balsam 674E 55.3' Found 5/8' Iron pin with 1.5' dia. iron cap stamped 'CF20' on bank of AR grade: NB3E 27.85' Bearings are magnetic. Found squared 4'

(C7) Found 1' dia. solid iron bar projecting 17'. 5' maple w/old blazes, nail and washer, N44E 20.9'
10' Spruce w/old blazes. Set nail and MDNR tag, S14E 20.6'
7' Maple N87W 19.9' marked "S18 MBT"
5' Maple w/old too blaze \$20W 13.6' marked "MBT"

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
LAND
SURVEYOR
LAND SPINSEN MAN