## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comens in	
Iron Located in: Corner Code #	
(County)	•
1. Public Land Survey	
2. Property Controlling       S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 6 5 4 3 2
Jul 01 1997	3 1 1 1 1 1
	4 7 8 9 10 11 12
stephan J. Szyszkoski , in a field survey on, 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	5
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or	6 18 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
recovered, found as expressed below.	8 -19 -20 -21 -22 -23 -24 -
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 34 35 36
(M5) Corner common to Sections 12-13 T44N-R31M, and Sections 7-18 T44N-R30M. Corner reestab proportionate measurement between corners 79.89 ch. North and 239.67 ch. South. The corner mitness corner placed on the section line S 0 deg 22 min M, 3.50 chains from the section corner, Enger placed a 1° I.O. x 36° iron pipe with 4° aluminum cap and marked the following M50M 39 links.	falls in a pond and was monumented by a ner. At the position for the witness
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn (MS) Recovered the 1969 monument as described, a 1° iron pipe capped with a cast aluminum ta	blet, squared, stamped "Wit. Cor. for
12-13-7-18 Cor. is No deg. 22'E 3.50 chains". The monument is in good condition and at recomitnesses recovered as follows: W. Pine 30" NI3E 19.0' found in good condition with blazes of only the notch visible. I determined via GPS observations that the extension of the section 20° M (true bearing), rather than Engers' bearing. I used my bearing, and the record 3.50 section corner for use in a partial subdivision of Section 13 during the course of this survice computed the distances to the corners noted in Part A above to be 79.85 ch. north and 239.52 careful and faithful reestablishment of the position of the corner. Left the Mitness Corner described below. Corner rewitnessed by B.Wheeler and D.Lamplela, Baraga District Office, MD	vergrown, M. Pine stump 17" M50M 25.8', I line from the south is actually M0 deg. 27 I chains in computing the location of the rey. From the Section corner in the pond, I I ch. south. I accepted Enger's corner as a I in place and marked 3 new accessories as
C. Description of monument for comer and accessories established to perpetuate locating the pos (N5) Found 1 pipe with 1 x2 square	ition of the corner:
aluminum tablet for a mitness corner.	THE OF MICHIES
Blazed and scribed the following:	STEDUL
14" N. Birch SO9E 24.1" "NC BT"	STEPHAN J. ** SZYSZKOSKI
30" N. Pine M26M 44.0" "MC BT"	LAND

Surveyor's Michigan License No. 33986

The 1969 wit: 30" M. Pine N13E 19.0'

Bearings are magnetic.

SURVEYOR

For the Michigan Department of Natural Resources - Forest Management Division