LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

corners	

Iron	Located In:	Corner Code #			
(County)					
1. Public Land Survey	T 44N R 31W T R	M12			
2. Property Controlling	s †				
in Section	S 36 T 44N R 31W S T R	L12			
3. Miscellaneous	s T R				
Property in Sec.	STR		Register of Deeds Stamp & File Number		
4 Let Ne Proported Plot					
5. Private Claims					
3.1111aco otamis	M12 (7/16/2008	2 - 6 - 1 - 5 - 1 - 4 3 - 1 - 2 - 1 - 1		
			3		
I, Stephan J. Szyszkoski, in a field survey on L12 07/23/2008 do hereby state					
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2					
above were in conformance with regulations and rules therefore as required in the current manual of survey 5					
instructions of the United States Department of the Interior, bureau of Land Management of by a decree of					
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8					
and the state of t					
re-established, monumented, recove	red, found as expressed below.		9		
			10 30 29 26 27 26 25		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			11		
on this certificate.			12 31 32 33 34 35		
			13		

A. Description of original monument and accessories and/or subsequent restoration: (M12) Quarter corner common to Section 36 T44N-R31W and Section 31 T44N-R30W. 2003 - Remonumented by G.L.Pisoni RLS. Approved by Iron Co. Peer Group Dec. 19, 2003 and recorded in L 10, Page 221, Iron County Records. Set 5/8" diameter x 30" rebar with Iron County Remonumentation cap. White Birch 11" S19W 24.37' (1963 NBT), Sugar Maple 9" N50W 36.51', Balsam 5" N37W 9.55', Sugar Maple 6" N21E 49.57', White Birch 15" N72E 1.90', Steel sign post S63W 0.90'.

- (L12) Center of Section 36. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (M12) Found the 2003 monument in good condition and at record bearing and distance from the witness trees of record, all in good condition but for the Balsam NW which is now standing dead. Marked a new bearing tree as described below.
- (L12) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M12) Fd. 5/8" rebar with Iron County cap. Set measuring nail with MDNR tag in the side of: 13" Sugar N23W 35.6' mrkd "1/4S NBT" 10" W.Birch S21W 24.4' "S36" 1963 NBT Fd. nail in mrkd "X BT" 16" W.Birch N67E 1.9' do 9" Sugar N46W 36.5' 13" Sugar N23W 35.6' do Steel sign post S63W 0.9'

(L12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:

mrkd "C1/4 BT" 7" Balsam N16W 26.7' do

8" Balsam N44E 24.45'

do 4" Tamarack S37W 37.25' do

4" Spruce N88W 22.1' Set sq'd cedar post adjacent. Bearings magnetic.

Bearings are magnetic.

33986

08/25/2008

Surveyor's Michigan/License No. For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD

16110

Date

LAND SURVEYOR No 1975 LANDS

STEPHAN J

YSZKOSK

16111