## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in Iron	Located In:	Corner Code ≠	•							
	(County)		33,110, 3333								
1.	Public Land Survey	T 45N R R R R R R R R R R R R R R R R R R R	CL								
2.	Property Controlling	S _6 T 45H R 31H S T R	1								,
3.	Miscellaneous Property in Sec.			Registe	r of C	eeds	Stamp	& File	Numt	700	<u>.                                    </u>
4.	Lot No,	Recorded Plat			A B	c o	E #	д н	Lj	<b>*</b> L	ш
5.	Private Claims			3					-		
do l in il cun Mar abo	nereby certify that under rines 1 and 2 above were rent manual of survey instrugement or by a decree over were in conformance to	, in a field survey on <u>April</u> equirements of P.A. 74, Michigan P.A. in conformance with regulations and tructions of the United States Depart of a Court of Law and/or that the corne with the rules of the Michigan Board o	of 1970, the corner points mentio d rules therefore as required in Iment of the Interior, Bureau of L ir points mentioned in lines 3, 4 a If Land Surveyors or by a Decree	oned g the 7 and 7 and 5 g	-19-	17-	16-	15-22-	23-		3 1

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

(CL) Section corner common to Sections 5-6, T45N-R31W, and Sections 31-32 T46N-R31W. Original corner established 1846 by U.S. Deputy Surveyor John Burt. Original BTs:Fir 14 N41E 23, Cedar 18 N71/2N 31, Y. Birch 12 S17E 29, Y. Birch 10 S62N 55. In 1935, B.C. Buell of Patten Timber Co. (now Hed Lake Land and Timber Co.) notes "Set cedar post" and that Cedar OBT was recovered "Down, I.M. plain". Found no subsequent record

(81) 1/4 corner common to Section 6 745M-R31M, and Section 31 746M-R31M. Original corner established in 1846 by U.S. Deputy Surveyor John Burt. Original BTs: Sugar 8 MilE 27, Spruce 10 M27M 26. in 1935, 8.6. Swall of Patten Timber Co. (now Med Lake Timber and Land Co.) motes "no trace" of the OBTs. Found no subsequent record.

(7-Sec. 6) North 1/16 corner between Sections 5-6. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C1) Recovered remains of old cedar post, down, at record bearing and distance from remains of original cedar bearing tree (down and in very poor condition, no iron earks visible), and at record bearing and distance from probable stump hale of the original fir BT. Original Y. Birch BY to SE not recovered, Y. Birch to SW would have been destroyed by an old skid trail. A Celotex location poster signed by a number of individuals, on an old 25° blazed cherry, faces the corner. At the position of the downed post, I placed a 1'x36' iron pipe, capped with a 4' dia. cast aluminum MOMR tablet, appropriately stamped.

(81) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner. Reestablished the corner on a straight line between section corner 2638.81' east and township corner 2655.30' west, being 40 chains, proportionate measure, west of the section corner. At the position for the corner, placed a 1"x36" iron pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped. From the corner monumented, found a 3/4" iron pipe, placed by unknown persons, M40M 18.9". (7-Sec. 6) Established the corner on a straight line between quarter corner 1321.02' south and section corner 1304.49' morth, being the proportionate position. At the position for the corner, I placed a 1"x36" iPon pipe capped with a 4" dia. cast aluminum MDMR tablet, appropriately stamped. From the corner monumented, an iron fence post, set in a rock mound, bears N72E 16.1'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (81) Set 1° pipe with 4° cap. (7-Sec. 6) Set 1" pipe with 4" cap. (C1) Set a 1"x36" pipe with 4" cap. Blazed and scribed the following new Blazed and scribed the following new Blazed and scribed the following bearing bearing trees (bearings magnetic): bearing trees (bearings magnetic): trees (bearings magnetic): '\$32 ND1' 5" spruce \$34E 3.2" "1/45 MBT" 15° Sugar \$56N 13.2' "1/165 BT" 25" Cherry N12E 4.9" 12" Maple H77W 29.7" "\$31 HBT" 4" maple \$650 20.4" "1/45 NBT" 12° Sugar N52E 11.3' "1/165 BT" Maple \$18W 16.4" "\$6 MBT" 6" spruce N56E 4.7" "1/45 MBT" 8" Sugar \$02W 15.4" "1/165 BT" 5" Sugar 852E 11.7" "85 MBT" 12 spruce N23N 4.6' "1/45 NBT" 10" Sugar NOSN 28.7" "I/16S B1" Set a squared post 1 ft, north.

Surveyor's Michigan License No.

LAND SURVEYOR STATE NAME OF LA

STEPHAN J. SZYSZKOSKI