(97)

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register of Deeds Stamp & File Number

4. Lot No. ______ , Recorded Plat ___

Property in Sec.

5. Private Claims

_ R _

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(83) Quarter corner common to Sections 6-7. Corner previously recorded in 1971 by Arthur O. Enger, RtS as follows: 1°1.0.x36° iron pipe with 4° aluminum cap placed at found coder post set from original 87. Witnesses to corner: Elm 8 N5 1/2W 22 links, N. Spruce 8 S76 1/2E 54 1/2 links, Found no subsequent record.

(D1) Quarter corner common to Section 5 T45M-R31W and Section 32 T46M-R31W. Corner established in 1846 by U.S. Deputy Surveyor John Burt. Original BTs: Lynn 9 M34E 24, M. Pine 7 M35W 32. Found no subsequent record.

(03) Quarter corner common to Sections 5-8. Corner established in 1849 by U.S. Deputy Surveyor John Burt. Original BTs: Sugar 12 HIOW 30, Sugar 14 S68M 31. Found no subsequent record.

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(83) Found and accepted the corner monument as described above at record bearing and distance from the ele MBT, now dead. The M. Spruce MBT was not recovered. Marked 4 mem bearing trees as described below.

(01) Original post and accessories not recovered. Found 2 old W. Pine stumps in the corner area but neither show signs of having been marked. Found no acceptable evidence of the position of the original corner. Reestablished the corner on a straight line between section corners 2640.96° east and west, being the proportionate position. At the position for the corner, I placed a 1°x32° iron pipe capped with a 4° dia. cast aluminum MDMR tablet, appropriately stamped.

(D3) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner. There was possibly a 1/2 error in the original measure on this line - it measures 0.68 ch. longer than record. Of 17 miles measured in this township during this survey, differences have typically ranged between -0.11 ch. and +0.13 ch. It was impossible to determine in which 1/2 mile the error was made and so the corner was reestablished on a straight line between section corners 2653.46' east and west, being the proportionate position. At the position for the corner, I placed a 1'x32" iron pipe capped with a 4' dia. cast aluminum MDMR tablet, appropriately stamped.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

STEPHAN J. SZYSZKOSKI

LAND

SURVEYOR

(83) Found 1" pipe with 4" cap. (D1) Set 1" pipe with 4" aluminum cap. Blazed and scribed the following new Blazed and scribed the following new bearing trees (bearings magnetic): bearing trees (bearings magnetic): 5" Maple MSOE 7.6" "1/45 MBT" 12" Sugar N22E 13.4" "1/45 MBT" 7" Sugar \$27E 9.4" "1/45 NBT" 5" Maple \$87E 9.5" "1/45 NBT" 14" Balsan \$63M 34.1" "1/45 MBT" "1/45 NBT" 10° Sugar \$880 3.5° 5" Sugar NOBN 24.5' "1/45 NBT" "1/4S NRT" 6" Sugar #30# 17.3" Set squared post adjacent to the corner. NSSE 1.7', squared a 4" Sugar.

(03) Set 1° pipe with 4° aluminum cap.
Blazed and scribed the following new
bearing trees (bearings magnetic):
3° R. Pine M37M 37.2° "1/45 MBT"
2° R. Pine M14E 22.4° "1/45 MBT"
2° R. Pine M47E 25.2° "1/45 MBT"
4° Poplar West 32.2° "1/45 MBT"
Corner falls on the division between a
R. Pine plantation north (2-4° dia.) and
a poplar regeneration south (1-2° dia.).

Signed by Light J. Surveyor's Michigan License No. 33.84

Date 6-28-93

FROM APPROVER BY MICHIGAN STATE GOARD OF LANG SURVEYORS, JAN. 26, 1871 REVISED MAT 14, 1975