## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

			1
Iron	Located In:	Corner Code #	
(County)	-		
1. Public Land Survey	T 46N R 33W T 46N R 33W T R	H1 G1	
2. Property Controlling in Section	S T R S T R S T R		
3. Miscellaneous Property in Sec.	S T R R		Register of Deeds Stamp & File Number
4. Lot No. , Red 5. Private Claims	corded PlatH1 08/	17/2009	A B C D E F G H I J K L M
above were in conformance with rinstructions of the United States II a Court of Law and /or that the countries of the Michigan Board re-established, monumented, recover NOTE: Not more than 2 corners	a field survey on G1 08/74, Michigan P.A. of 1970, the corner regulations and rules therefore as required pepartment of the Interior, Bureau of Lorner points mentioned in lines 3, 4 and 1 of Land Surveyors or by a Decree	points mentioned in lines 1 and 2 and 1 and 2 and 3 and 3 and 4 and 4 and 4 and 4 and 5 and 5 and 6 an	y 5 of 6 h 7 1, 8 19 10 30 29 28 27 26 25 11
on this certificate.			12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (H1) Quarter corner common to Section 34 T47N-R33W and Section 3 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Spruce post. Spruce 8" N55E 47 links, Fir 6" N22W 45 links. Found no subsequent record.
- (G1) Corner common to Sections 33-34 T47N-R33W and Sections 3-4 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Maple post. Maple 8" N35E 25 links, Y.Birch 12" N55W 26 links. 1852 Francis Houck Deputy Surveyor marked Fir 12" S12W 29 links, Spruce 12" S64E 37 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (H1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 7906.78' east and Township corner 18332.52' west.
- (G1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 10542.37' east and Township corner 15696.92' west.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (H1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 16" Tamarack S55W 43.65' mrkd "1/4S NBT" 3" Balsam N47W 15.75' do 5" Balsam N04W 46.3' do 4" Balsam N17E 54.1' do Set sq'd cedar post near. Bearings magnetic.
- (G1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap made firm in a mound of rock.

  Set measuring nail with MDNR tag in the side of:
  6" twin Maple N13E 22.1' mrkd "S34 NBT"
  7" Balsam S82E 12.7' "S3 NBT"
  10" Maple S30W 21.35' "S4 NBT"

Set sq'd cedar post near. Bearings magnetic.

Signed by Stephen Synglish 33986

Date

5" Maple S66W 30.35'

10/06/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD CORP.

AND Bearsed by 14, 1975

Rervised Oct., 1995

"S4 NBT"

STEPHAN J

SZYSZKOSK LAND

URVEYOR

16315 16316