LAND CORNER RECORDATION CERTIFICATE

For corners in	Filin	g Requirement of Act 74, M	ich. P.A. 1970				
[County)	Located in:	Corner Code #	ļ				
1. Public Land Survey	T <u>46H</u> R_ T <u>46H</u> R_ T R_						
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_		Re	gister of Dec	ds Stamp &	File Nu	mber
4. Lot No, Reco	rded Plat		- <u>, , , , , , , , , , , , , , , , , , ,</u>	CDE	г в н	1 J K	. T.
		Aug 04 1998 Aug 13 1998	- 1 2 3	5	3-	2 -	_
conformence with regulations and United States Department of the I that the corner points mentioned	, in a field survey on _ an P.A. of 1970, the corner I rules therefore as required interior, Buresu of Lend Ma in fine 3, 4 and 5 above w y a Decree of a Court of	points mentioned in lines 1 and 2 a in the current manual of survey instra ragement or by a decree of a Court of the conformance with the rules of a Law; established, re-established, n	bove were in uctions of the 5 11 11 11 11 11 11 11 11 11 11 11 11 1	0 17	16 15	-14	-12-
NOTE: Not more than 2 com on this certificate.	iers, all in the same town	and range, may be recorded	9 10—30 11—12—31	29 32 32	28 27 34	-26 -35	—25— —36—
 Quarter corner common to 	Section 19, T46M-R34W	and/or subsequent restoration: and Section 24 T46N-R35N. Co of hill. Fir 12 SSSE 5, Real	rner established in	1846 by Wa.	A. Burt: "No dated 1/24/	<u>l_l</u> orth 1934 on	_1_

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

S40E 28, do 12 M23W 28. Found no subsequent record.

(A8) Original post and accessories were not recovered. Cedar and stake noted in the 1934 cruiser report were not recovered. Found no acceptable evidence of the position of the original corner on the ground. I reestablished the corner on a line of mean true bearing between Section corners 39,9143 chains north and south (40.00 ch. GLD). I observed the bearing along this line to be only 3 arc-seconds west of true north. At the position for the corner I placed a 1° I.D. x 32° iron pipe capped with a 4° dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and mitnessed by O.Lampela and B.Wheeler, Baraga District Office. (66) Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reastablished the corner midway and on a line of mean true bearing between Section corners 40,083 chains north and south, being proportionate to the original record. At the position for the corner, I placed a 1° ID x 32° iron pipe capped with a 4° dia. cast aluminum MOMR tablet, appropriately stamped. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

file with the USFS Surveyor at Ironwood, MI are not clear but seem to state : "Fd. Cedar stake good condition with scribing [unclear

(G6) Quarter corner common to Sections 15-16. Established in 1852 by Zelotes B. Searles: "40.00 Spt quarter Section post. Cedar 14

whether scribing is on post or a tree]. Post is S ft. south of 7° cedar. Believe GLO°. Found no subsequent record.

C. Description of monument for corner and a	accessories established to perpetuate locating the	position of the countries
(AB) Set 1" pipe with 4" MONR cap.	(66) Set I" pipe with 4" MONR cap.	position of the control
Blazed and scribed the following:	Blazed and scribed the following:	
14" Y. Birch NO7E 42.0'* "1/45 NBT"	10° Cedar N6SE 17.85' "1/45 NBT"	* STEPHAN J. *
17" Healock \$22E 17.8" do	10" Cedar SOLW 35.6' do	* SZYSZKOSKI
10" W. Spruce \$08W 44.3"* do	13° Cedar NB4W 46.55' do	LAND
16" Y. Birch H49W 20.0'* do	10° Cedar N23M 37.1' do	SURVEYOR
Placed a squared cedar post adjacent.	Placed a squared cedar post adjacent.	No.
Distances are to meas, notch. Bearings	Bearings are magnetic. Distances are to	33986
are magnetic. Dist. noted with # are	meas. notch.	
measured along the slope.	•	
00-011		
Signed by Stephen J. On	Shol. Date	12/29/98

33986 Surveyor's Michigan License No.