LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•	•	1						
Iron	Located In:	Corner Code #							
(County)	_								
1. Public Land Survey	T_46N_R_ TR_ TR_								
Property Controlling in Section Miscellaneous	S TR_ S TR_ S TR_		:						
Property in Sec.	S TR_			Registe	er of De	eds St	amp &	File N	lumber
4. Lot No, Reco	rded Plat		<u>بر</u> ا 1	. B C	D E	F C	5 H	<u> </u>	K L I
		Aug 18 1998	2 3	-6-	-5- 	-i-	— <u>3</u> —	<u>├</u> - <u>}</u> -	
t Stephan J. Szyszkoski	, in a field survey on _	19 do hereby state the	et under (ا ۔۔۔ ا ا	10	-¦-	12-
conformance with regulations and United States Department of the that the corner points mentioned	d rules therefore as required Interior, Bureau of Land Ma 1 in lines 3, 4 and 5 above w	In the current menual of survey instruction negement or by a decree of a Court of Law wre in conformance with the rules of the M	ns of the 5 rand for 6 fichigan	-18	_12_	_16	— —15—	14-	13
Board of Land Surveyors or by recovered, found as expressed by		Law; established, re-established, monur	mented, B	_19_	_20_	_21_	22	23-	2,4-
NOTE: Not more than 2 con on this certificate.	ners, all in the same town	and range, may be recorded	9 4 10	30	_29_	_28_	27	26-	25-
			11 12	-3 1	-32-	_33		35_	36
		e and/or subsequent restoration: 24-25 T46N-R35N. Corner establish	13 ^L hed in 1846 b	y Va. f	. 8urt:	* Nort	h, 8	0.00 \$	<u> </u>

(A9) Corner common to Sections 19-30 T46M-R34W and 24-25 T46M-R35M. Corner established in 1846 by Mm. A. Burt: "Morth... 80.00 Set maple post cor. of secs. 24 and 25. Lynn 18 M72E 22, Memlock 20 M72M 25." Further 8T by Z.B. Searles in 1851: Y. Birch 10 S31E 23. Cruiser notes dated Jan. 20, 1934 on file at the office of the USFS Surveyor in Ironwood show: "Hemlock good condition 7" above ground [?] no iron marks. Tag on S. side of tree. Blazes and markings on tree by LES. Clarence Jones 1/20/34"

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

(A9) Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Hear the corner position, I found two blazed and painted Hemlocks and a triple 19" basswood with a very old forest Service location poster attached. Painted blue lines run North and East from one of the Hemlocks, which bears M52E 34.5" from the position subsequently monumented. The blazes date back to around 1958, by count of the growth rings. I reestablish the corner by single proportionate measurement to the original record, on a line of mean true bearing between USFS monument for Quarter corner 39.9146 ch. South and USFS monument for Section Corner 79.8287 ch. North. I observed the bearing of this line to be 4 arc-seconds West of true North. "At the position for the corner I placed a 1" I.O. x 32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and witnessed by D.tampela and B.Mheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate	locating the position of the continue
(A9) Set 1° pipe with 4° MONR cap.	25
Blazed and scribed the following:	
10" Memlock N52E 34.5'(slope)"S19 N8T"	STEPHAN J.
10° Y. Birch S45E 10.2' "S30 MBT"	SZYSZKOSKI T
20" Hemlock SOBN 33.3' "S25 MBT"	* LAND
10" Y. Birch W16W 3.2" "\$24 W8T"	SURVEYOR
The 20° Heml, has an old "beaver" facing	No.
NNE. Placed a squared cedar post	33986
adjacent. Distances are to meas. notch.	TO CHANGE TO SERVICE T
Bearings are magnetic.	

Signed by tesh 1. Smpshale'
Surveyor's Michigan Ucense No. 33986

Date 12/29/98

for the Michigan Department of Matural Resources - Forest Management Division