JACKSON COUNTY NORTHWEST CORNER. PROVED LAND CORNS HENRIETTA TOWNSHIP Chairman LAND CORNER RECORDATION CERTIFICATE #2044414 Filing Requirement of Act 74, Mich. P.A. 1970 Liber 1549 Page 134 or corners in Page 1 of 1 JACKSON Jackson Co., MI Located In: Corner Code ## (County) Recorded SURVEY & 08/15/97 10:56A TISRIE K-1 **Public Land Survey** REMONUMENTATION Mindy Reilly T _____ R _ Register of Deeds R. APR 0 7 1998 R _ R _ **Property Controlling** Т S __ T _ _ R _ in Section SECTION _ R _ Miscellaneous S Т Register of Deeds Stamp & File Number R Property in Sec. _ , Recorded Plat . Private Claims

DEAN R. GUTEKUNST in a field survey on July 15, 1996 & August 8 a hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 pove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as (pressed below:

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Original Government Post set by Joseph Wampler, Deputy Surveyor, October 1825.

191 links (12.54') 80 links (52.80') W. Oak 22" S 25 E W. Oak 12" S 80 W

90, Intersect Town on Base line

Stone post has been kept.

10

11

12 13

Perpetuation by H. F. Bean, 1888.

S 11 3/4 E $288\frac{1}{2}$ links (190.41') Maple 12"

Hickory 8" N 79 E $241\frac{1}{2}$ links (159.39')

Not recorded in P. A. - 74.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found bottom 11" of a Fireclay, with 6" mid section above. Top of fireclay was missing. Found broken brick around bottom of fireclay.

Corner was approximately on center line of Base Line Road (gravel) and approximately 3' West of center line of Fitchburg Road (blacktop) running South.

Road was relocated Southerly, at intersection, when paved, and corner is now 9't North of blacktop.

Accepted Fireclay as a careful and faithful perpetuation of the position of the original corner as remonumented by Bean in 1888.

Set a Standard Jackson County Monument to replace the fireclay and left fireclay buried on the North side.

NOTE: The Ingham County line has not been remonumented at this point.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 4" diameter X 36" concrete monument with a $\frac{1}{2}$ " X 36" steel TIS, RIE rod and an aluminum cap stamped LS 18658, which is a standard monument for Jackson County.

Utility Pole N 600 W 188.38' Pole barn spike and washer on Northeast side. N 65° E 232.26 Utility Pole Pole barn spike and washer on South side. S 35° E TOF MICH Southwest corner of a small frame shed 180.70' N 75° E 78.1 center line of a metal Bell box Steel post and survey marker sign attached

North

18658

veyor's Michigan License No. _

August 1, 1997 ned by

FORM APPROVED BY MICHIGAN STATE BOARD

Texord 314

PROPERTY SED MANY 14, 1975 REVISED JAN., 1983

GUTEKUNST

ALIEVE MUNICIPAL SUA