JACKSON COUNTY APPROVED LAND CORNER P.A. 345 of 1999 - North 1/4 Corner of Section 24, Henrietta Township Chairman Wes LAND CORNER RECORDATION CERTIFICATE Date MAL. Filing Requirement of Act 74, Mich. P.A. 1970 #2064437 For corners in Liber 1563 Page 983 <u>JACKSON</u> Located in: Corner Code # Page 1 of I Jackson Co., ∦I Recorded 1. Public Land Survey R1E SURVEY & 03/12/1998 12:00P REMONUMENTATION Mindy Reilly Register of Deeds 2. Property Controlling SEP 1 16 1998 in Section 3. Miscellaneous Property in Sec. SECTION Register of Deeds Stamp & File Number Lot No. Recorded Plat 5. Private Claims ₿ C Đ Ε F Ģ Н J K 2 6 5 å 3 2 1 3 4 7 8 Ģ 10 David E. Erickson, in a field survey on November 13 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned. 11 12 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land ò 18 17 15 16 14 13 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of 0 10 วก 21 22 23 24 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 9 70 30 29 28 27 26 25 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 31 32 33 34 35 36 Description of original monument and accessories and/or subsequent restoration; 13 Around 1825, Joseph Wampler - Deputy Surveyor, set a "Post at aver dist" and recorded two witnesses: "Elm 20, N42°W, 12" (7.92') and "Ash 15, S42°W, 5" (3.30'). Around 1888, H.F. Bean reported "Post gone, Established this corner 80.35 is the length of section line" and recorded two witnesses: "Swp. Oak 5, S68 3/4°E, 78" (51.48') and "Elm 4, N34°E, 57" (37.62'). In 1994, A.L. Scheppleman recorded this corner in Liber 4, Page 267, as "found 1/2" capped rerod 1.5' S. of centerline E-W road." Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a 1/2" rebar near road centerline, at surface. Survey by Hughes, Keller and Scheppleman have utilized this corner. Corner is over a metal culvert, near centerline of a N-S drain, in 3' to 4' fill. Found no other evidence of corner monument. Did not excavate area. Believe any corner evidence would have been destroyed in either ditch construction or culvert installation. Accepted found iron as the best available evidence of the position of the original corner. Set a 30" long Harrison cast iron monument with Cap exact location of found iron. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set a 30" long Harrison cast Iron monument with Cap stamped "#29245". N 22° E Set nail & tag #29245, East side 9" Oak 30.11 N 67° E Set nail & tag #29245, Southeast side 30" Hickory 50.26 5 01° E Set nail & tag #29245, West side 20" Maple 32.25' E OF MICHIGAN attiffffer. S 57° W Set nail & tag #29245, Northwest side 24" Oak 59.44 S 17° W County Surveyor sign post 22.34 NOTE: Bearings are magnetic DAVIDE ERICKSON S89°34'30"W K-7, Harrison monument Land Surveyor 2656,55' 29240 LAND SUR N89°34'17"E M-7. Harrison monument 2656,631

igned by Law E. Euchsm Date 3-11-98

Surveyor's Michigan License No.

form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

REVISED MAY 14, 197 REVISED JAN., 198 ROCESSING MARCH, 198