JALILL. .. JUNTY APPROVED LAND CORNER

Date NOU

Private Claims ____

P.A. 345 of 1990 Chairman Klan

29,1995

BORNELS TO

LIBER 1501 PAGE 785

WEST & POST, SECTION 33, RIVES TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	<u>-</u> -	•	
Jackson	Located in:	Corner Code ##	STATE OF MICHIGAN JACKSON COUNTY
	1 1ne	= 10	RECORDED
 Public Land Survey 	T <u>1s</u> R <u>1w</u>	E-12	
	T R		28 DEC 95 11:17 A.H.
	T R		
	T R		GERALD J. McDEVITT
2. Property Controlling	S T R		REGISTER OF DEEDS
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	\$ T R		

, ₁₉ _95 November 20 I, Alan L. Scheppelman in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

HERVEY PARKE

SET GR. SEC. POST

MARCH 17, 1825

Y. OAK 24, NORTH, 618 LINKS; NO OTHER TREE NEAR

H.F. BEAN

FOUND OLD STAKE AND BOTH WITNESSES (?), POST IS IN THE DITCH

1885

HICKORY 20, N14LE, 461 LINKS; BURR OAK 10, N6°W, 772L LINKS

CONTINUED ON BACK

\$ 2.00 REMONUMENTATION

\$ 9,00 CORNER RENONUMENTATION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND "T" IRON AND 3/4" PIPE ALONGSIDE OF A "T" FENCE POST IN A GRASS MARSH. EXCAVATED AN AREA 4' TO THE SOUTH, 6' TO THE WEST, 6' TO THE NORTH, AND 12' TO THE EAST AND DID NOT FIND ANY EVIDENCE OF THE FIRECLAY. FROM INFORMATION PROVIDED BY RON ENGER, IT WAS DETERMINED THAT A MIDWAY AND ON LINE POSITION WOULD BE WITHIN 0.2' EAST & WEST AND 2' NORTH & SOUTH OF THE "T" IRON. ACCEPTED THE "T" IRON AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. LEFT THE 3/4" PIPE AND "T" IRON IN PLACE AND DROVE A 1" x 60" ALUMINUM ROD IN THE POSITION OF THE "T" IRON.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NORTH	EAST-WEST FENCE	8.0	A VENT
NORTH	T FENCE POST	0.2'	SCHEPPELM
s60°E	NAIL & TAG #35998 IN SOUTH SIDE OF 12" WILLOW	65.44'	* PROFESSION
s30°E	NAIL & TAG #35998 IN NE SIDE OF 12" WILLOW	61.55'	SURVEYOR
s50°W	NAIL & TAG #35998 IN NW SIDE OF 8" POPLAR	54.47'	No.
SOUTH	SURVEY MARKER SIGN	3.0	POFFCCION

35998

Signed by Wan A Surveyor's Michigan License No. _

E-12, T1S, R1W

A. RICHARD GUTEKUNST

JAN. 22, 1974

RLS #7863

FOUND "T" IRON IN DITCH

SET 3/4" x 3' IRON ON NORTH SIDE

ON FILE AT GUTEKUNST SURVEYORS

NORTH 40" OAK 341.9'

8'± SOUTH OF EAST & WEST FENCE 13't WEST OF ROW OF TREES NORTH

RONALD L. ENGER

CERTIFICATE OF SURVEY RECORDED IN L. 1252, P. 450

L.L.S. #28409

FOUND T IRON

AUG. 13, 1990

FOUND 3/4" PIPE, IMMEDIATELY SOUTH

FOUND T SECTION FENCE POST, NORTH 0.2.