JACKSON COUNTY APPROVED LAND CORNER							
	n 9 Tamanlaina 77.		SU	RVE	Y &		,
Chairman West 1/4 Corner of Section 8, Tompkins Township EMONUMENTATION LAND CORNER RECORDATION CERTIFICATE							
			ł A RE	2 %	1000		
Filing Requirement of Act 74, Mich. P.A. 1970 JAN 2 7 1999 For corners in							
Located in: Corner Code #		SECTION					
1. Public Land Survey T1S R2W C-4							
TR					Page	7028	
2. Property Controlling S T R		Co.	CORRE	 -		9/1998 580	
3. Miscellaneous S T R	1			i			
Property in Sec. S T R R Register of Deeds Stamp & File Number							
4. Lot No Recorded Plat							
	2	6	5		3	2	1
) People C Existence	3						
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the coin lines 1 and 2 above were in conformance with regulations and other conformance.		' '	8	9	10	1:1	12
current manual of survey instructions of the United States Department of the Interior, Bureau of Land			17	16	15	14	13
Court of Law established re-setablished manufacture board of Land Surveyor	ed in lines 3, 4 and 5 7 rs or by a Decree of a	1 1	20	21	22	23	24
, · · · · · · · · · · · · · · · · · · ·	9		\dashv			-,-	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.		1 00 1	29	28	·27	26	25
A. Description of original monument and accessories and/or subseq	uent restoration:	31	32	33	34	35	36
	19			<u> </u>			·
In 1825, L. Lyon - Deputy Surveyor, set "Post" and lists two witnesses: "W. Oak 11, S56 1/2°E, 59" (38.94') and "do 10, S64°W, 35" (23.10'). In 1886, J. Holcroft, indicates the corner as "Found no trace of either corner or witnesses: measured transit line between sec 7 & 8 to 80.53 - Set post at average distance 40.26 1/2 (1995) which agrees with fence going west.", and lists two witnesses: "Hickory 5, S25 3/4°E, 101 1/2" (66.99') and "Butternut 6, N89°W, 141 1/4" (93.22'). Not recorded under Public Act 74.							
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found rebar at road surface. Excavated 3' square hole. Found intact Fire Clay (FC) below rebar and 1.5' deep. Pieces of brick around FC. Traces of wire in ground point Month.							
brick around FC. Traces of wire in ground going West. Accepted found FC as a careful and faithful perpetuation of the original corner as re-established by Holcroft. Replaced FC with a standard Harrison cast iron monument, down 04'. Buried FC and rebar on North side of monument.							
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:							
Set Harrison Monument with Jackson County Remonumentation Corner Cap stamped "LS #29245".							
S 35° W Set nail and tag #29245, East side 24" Cak S 85° W Set nail and tag #29245, North side 16" Welcott	39.28'	نع.		F MIA	City Control		
N 11° W Set nail and tag #29245, East side power pole	31.56' 132.85'	SALE S	VIC.	••••••	"ICAN	للعلين	
N 54° W Northeast corner of House #11522 N 85° W Southeast corner of House #11522	129.0' 106.1'	A A	DA	VID E. CKSON		A THE	
NOTE: Bearings are magnetic		*** LICE	l and	Surveyo No.		Manager A A A A A A A A A A A A A A A A A A A	
		THE CENT	SED L	9245	· K	A. C.	
O AO .		THE STATE OF THE S	ED L	AND S	University	5"	
Signed by tau culson Date	9-8-98			,	•		
Surveyor's Michigan License No. 29245 FORM APPROVED BY MICHIGAN STATE BOARD OF LINE SURVEYORS, JAIN 26, 1971							
		Anam	7EN BNO	7	EVISED MA	Y 14, 187: JAK., 1861	