Jackson Louniy APPROVED LAND CORNER P.A. 345 of 1990 **WEST 1/4 CORNER SECTION 1** Chairman **TOMPKINS TOWNSHIP** Date LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For comers in \_JACKSON Located In: Comer Code # (County) 2099034 Public Land Survey Page: 1 of 1 T<u>1\$</u> R<u>2W</u> 12/21/1998 10:57A L-1589 P-278 R 2. Property Controlling R in Section R 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number Lot No. \_, Recorded Plat K, L M 5. Private Claims t, DAVID L. CLIFFORD , in a field survey on OCTOBER 22 , 19 97 do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were 12 in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree 15 of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 30. 25 10 -28 27--26 --35 36--Description of original monument and accessories and/or subsequent restoration: ORIGINAL POST SET BY LUCIUS LYON D.S. IN FEB. 1825; W.O., 22", N89E, 9, W.O., 22", 2. IN NOVEMBER 1885 JOHN HOLCROFT REPORTED: "FOUND 1ST WITNESS STUMP AND REMAINS OF 2ND WITNESS: DBL B.O. 18", N48E, 7; HICK. 10", S7E, 291/2
3. CONSUMERS POWER COMPANY SURVEY OF THEIR FEE STRIP IN SECTION 1 SHOWS A MONUMENT AT K-2 BUT DOES NOT DESCRIBE IT OR GIVE WITNESSES 4. THIS SURVEYOR TRAVERSED TO CORNER IN OCTOBER 1988 WHILE WORKING ON THE SUPER CONDUCTOR SUPER COLLIDER SURVEY. I 4. THIS SUPVEYOR TRAVERSED TO CORNER IN OCTOBER 1988 WHILE WORKING ON THE SUPER CONDUCTOR SUPER COLLIDER SURVEY, I FOLIND A "T" IRON WITH CONSUMERS CAP ON THE EAST SIDE OF A RAILROAD TIE ANCHOR POST AND TOOK 4 WITNESSES: NAIL & TAG IN RAILROAD TIE FENCE POST, N2°E, 19, 10°; NAIL & TAG IN RAILROAD TIE FENCE POST, S85°E, 25.50°; SW LEG TRANSMISSION TOWER, N48°E, 182.80°; EAST CORNER POLE BARN, S25°W, 219...20°

5. MARK FAUSER IN THE EMPLOY OF HIS FATHER, GLENN FAUSER RLS # 18657, OBTAINED MY 1988 INFORMATION FROM MY FILES IN JULY 1997 AND UPON LEARNING THAT I PLANNED TO EXCAVATE CORNER EXCAVATE AROUND IRON AND REPORTED TO ME THAT HE HOLD FOUND A REPORTED TO ME THE TOWN AND THE T BROKEN FIRECLAY AND NUMEROUS PIECES OF BROKEN BRICK MIXED IN WITH STONES AROUND RAILROAD RAIL FENCE POST. HE SET A 1/2" BAR & CAP IN PLACE OF THE 'T' IRON. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;
SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND ½" BAR & CAP #18657 AT THE REMAINS OF A OLD FENCE CORNER MATCHING 2 OF MY 1988 WITNESSES, ACCEPTED BAR & CAP AS PERPETUATION OF CORNER BASED ON MARK FAUSER'S REPORT OF EVIDENCE FOUND IN EXCAVATION, WHILE EXCAVATING TO SET MONUMENT FOUND 2 PIECES OF BROKEN FIRECLAY, SEVERAL PIECES OF BROKEN BRICK AND A DEPOSIT OF LIME 30" DEEP AROUND IRON. SET STANDARD CONCRETE MONUMENT 18" DEEP. AS THIS IS NOW OPEN FIELDS DID NOT SET SIGN &

POST.

Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-2 T1S R2W 4" X 36" CONCRETE MONUMENT WITH ALUMINUM CAP STAMPED 25837

NAIL & TAG #28409 IN EAST ROOT 16" HICKORY, N3°E, 234.82" NAIL & TAG #28409 IN EAST ROOT 12" HICKORY, N1°E, 227.2 NAIL & TAG #28409 IN EAST ROOT 7" HICKORY, N25°E, 242.06" 227.25 SW CORNER SW LEG TRANSMISSION TOWER, N48°E,

NW CORNER POLE BARN, \$24°W, 219.42

Surveyor's Michigan License No. 25837

Daid L. Cliffon

Date NOVEMBER 17, 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14.1975

REVISED JANI, 1983 REVISED OCT., 1995

OF MICHIES

DAVID L

CLIFFORD

LAND SURVEYOR

NO.

25837

LAND

FAFD