Chelman Commert Commer	JACKSON COUNTY APPROVED LAND CORNER P.A. 343 of 1990 A A South 1/4 Common of South 2 A A A South 1/4 Common of South 2 A A A South 1/4 Common of South 2 A A A A A A A A A A A A A A A A A A	Der.		AVE		rian		
Filing Requirement of Act 74. Mich. P.A. 1970 For comes in JACKSCN Located In: Comer Code # SECTION 1. Public Land Survey T3S. R1E	The state of the s	new.	يَّا اللهُ يَهُ وَمِينَا لِمَا اللهِ	JW II	M JA	11,014		
Filing Nequirement of Act 74, Mich. P.A. 1970 1. Public Land Survey Tab. Pile The Receipt Controlling Same Recorded Plat 1. Public Land Survey Tab. Pile The Receipt Recorded Plat 1. David E Erickson in a field survey on Fabruary 10 19 97. 1. David E Erickson in a field	- 4.0 <u>Say - 7.1110</u>		.IAN	27	1000			
1. Public Land Burvey T3S R1E H3 Rindy Railly - Javisson Co. Coests 1. Public Land Burvey T3S R1E Rindy Railly - Javisson Co. Coests 1. Public Land Burvey Ragister of Deeds Stamp & File Number 1. Ragister of Deeds Stamp & File Number Ragister of Deeds Stamp & File Number 1. Devid E Erictson, in a find survey or February 10 1. Devid E Erictson, in a find su			33 L-31 A	ii	1333			
2. Property Controlling S T R S S T R S S T R R S S T R R S S T R R R S S S T R R R S S S T R R R S S S T R R R R	JACKSON Located In: Comer Code # 1 SECTION							
2. Property Controlling S T R R S Mindy Resist - Jackson Co. Conser L-1598 P-598 in Section S T R R R S Mindstaneous S T R R R Register of Deeds Stamp & File Number Register Registe	7.35 R1E H-3 Page: 1 of 1 Page: 11:81							
A. Lot No. Recorded Pial 5. Private Claims A. B. C. D. E. F. G. H. I. J. K. L. 1. David E. Erickson, in a field survey on February 10 19 97 of needly certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned and private or the private of the private o	7 R Mindy Reilly - Jackson Co. CORREM L-1580 P-509 2. Property Controlling S T R							
5. Private Claims A B C D E F G H J J K L 1. David E Erickson, in a field survey or Estruary 10 16 97 to hereby certify that under requirements of P A 7. A foreigne P A of 1970, the corner points mentioned in lines 1 and 2 show were in continuous of P A 7. A foreigne P A of 1970, the corner points mentioned in lines 1 and 2 show were in continuous of P A 7. A foreigne P A of 1970, the corner points mentioned in lines 1 and 2 show were in continuous of the United States Department of the broken as required in the current manual of survey instructions of the United States Department of the broken as required in the current manual of survey instructions of the United States Department of the Broken as required in the current manual of survey instructions of the United States Department of the Broken as required in the current manual of survey instructions of the United States Department of the Broken as required in the current manual of survey instructions of the United States Department of the Broken as required to the Corner of the United States Department of the Broken of the Corner of the United States Department of the Broken of the United States Department of the Un	Property in Sec. S T R Register of Deeds Stamp & Sile Number							
I. David E. Erickson: in a field survey on February 10 1s 97. of hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 shows were in conformance with regulations and niles therefore as requirement of survey inclusions of the United States Department of the intensity. Biseau of Land allows the Court of Law, established, re-established, survey and the results of the Court of Law, established, re-established, monumented, re-monumented, re-monumented	4. Lot No, Recorded Plat							
1. David E. Erickzon, in a field survey on February 10 19 87. do hereby certify that under requirements of PA 74. Michigan PA of 1910, the comer points mentioned in lines 1 and 2 above were in contramance with regulations and rules therefore as required in the same to the corner points mentioned in lines 1 and 2 above were in contramance with regulations and rules therefore as required in the same forms of the corner points mentioned in lines 1 and 2 above were in contramance with regulations and rules therefore as required in the corner points mentioned in lines 3, 4 and 5 18 19 10 11 12 12 12 12 12 12 12 12 12 12 12 12	v. Firede Ganis	A B	C D	E F	<u>Б</u> Н	J K	<u> </u>	
I. David E. Erickzon, in a field survey on February 10 19 97. To history cortify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned control from the control manus and rules therefore as required in the comer control from the control from the regulations and rules therefore as required in the comer control from the rules of the district of the Catasta Department of the intestor, Bureau of Land Management or by a decree of a Count of Law, established, re-established, monumented, re-monumented, re-monumented		6	5	4	3	2	1	
rement manual of survey need all commontance with regulations and rades therefore as required in the Management of by a decree disclose of the United States begentered of the intention, Bureau of Land Advancement of by a decree disclose of the United States begentered of the intention, Bureau of Land Advancement of the Management of Land Surveyors of by a Decree of a above were in conformance with the nates of the Missian Burard of Land Surveyors or by a Decree of a control Carlo Surveyors or by a Decree of a control Carlo Surveyor or by a control Carlo Surveyor or control Carlo Surve	1, <u>David E. Erickson</u> , in a field survey on <u>February 10</u> 19 97	7	. 8	9	10	31	12	
expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this estificate. A. Description of original monument and accessories and/or subsequent restoration: Around 1825, H. Parke - Deputy Surveyor, "Set Post at siver. dist." and recorded two witnesses: "Y. Oak 28, S87°E, 81" (53.46") and "W. Oak 30, West, 43" (28.38"). Around 1888, H.F. Bean reported "post standing found remains of both witnesses. The section line is the South line of road". Also notes 2 witnesses: "Hickory 10, S1"W, 235" (155.10") and "W. Oak 2, N85 M*PE, 57" (37.62"). A corner index card of Jackson County Road Commission (JCRC) reports "Firecisy post 24.60" South of centerline of Page Ave." and lists 4 witnesses: "16" Maple, N.35"W., 59.1; NW cor. House, S.37"W., 74.0; NE cor. House, S.22"W., 65.1; End fence Post, South, 33.0". In 1972, F.E. Spicer - R.S. 87877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: 385"W, Nail C/L. CP/MBT pole, 20.85"; S15"W, NE cor cone bik find, 54.45"; N0", S edge bikty pavt, 15"; N 45"W, Nail C/L. 20" Maple, 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Kelter - RLS \$20707, recorded the corner as "Found capped iron & fineclay" and lists 3 witnesses: "north, centerline blacktop, 25.5"; S85"W, power pole, 20.80"; S10"W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Burled FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 38" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 19	Current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corresponds mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Minhites Roand of Land Survey were 1, 2, 2, 3, 3, 4, 3, 4, 3, 5, 5, 5, 5, 5, 6, 7, 7, 8, 7, 8, 8, 9, 10, 10, 10, 10, 10, 10, 10, 10, 10, 10	18	17	16	15	14	13	
NOTE: Not more than 4 corners, all in the same form and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Around 1825, H. Parke - Deputy Surveyor, "Set Post at aver. dist." and recorded two witnesses: "Y. Oak 28, S87°E, 81" (53.48") and "W. Oak 30, West, 43" (28.38"). Around 1825, H.F. Bean reported "post standing found remains of both witnesses. The section line is the South line of road". Also notes 2 witnesses: "Hickory 10, S1°W, 235" (155.10") and "W. Oak 2, N85 3/4°E, 57" (37.62"). A corner index card of Jackson County Road Commission (JCRC) reports "Fireclay post 24.80" South of centerline of Page Ave." and lists 4 witnesses: "16" Maple, N.35°W, 59.1; NW cor. House, S.37°W., 74.0; NE cor. House, S.22°W., 65.1; End fence Post, South, 33.0". In 1972, F.E. Spicer - RLS 87877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: 985°W, Nail C/L CP/MBT pole, 20.85'; S15°W, ME cor cone bik fnd, 54.45'; N0°, S edge biktip pavt, 15'; N 45°W, Nail C/L 20" Maple, 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Keller - RLS \$20707, recorded the corner as "Found capped Iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5'; S85°W, power pole, 20.80'; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 1997". S 35° E Set nai	expressed below.	19	20	21	22	23	24	
Around 1825, H. Parke - Deputy Surveyor, "Set Post at aver. dist." and recorded two witnesses: "Y. Oak 28, S87°E, 81" (53.46") and "W. Oak 30, West, 43" (28.38"). Around 1888, H.F. Bean reported "post standing found remains of both witnesses. The section line is the South line of road". Also notes 2 witnesses: "Hickory 10, S1°W, 235" (155.10") and "W. Oak 2, N85.34°E, 57" (37.62"). A corner index card of Jackson County Road Commission (JCRC) reports "Firecisy post 24.60' South of centerline of Page Ave." and lists 4 witnesses: "16" Maple, N.35°W., 59.1; NW cor. House, S.37°W., 74.0; NE cor. House, S.22°W., 65.1; End fence Post, South, 33.0". In 1972, F.E. Spicer - RLS \$7877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: S85°W, Nail C/L CP/MBT pole, 20.85'; S15°W, NC cor conc bik fnd, 54.45'; N0°, S edge biktip pavt, 15'; N 45°W, Nail C/L 20" Maple, 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1978, R.W. Keler - RLS \$20707, recorded the corner as "Found capped Iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5'; S85°W, power pole, 20.80'; S10°W, Northeast corner house, 54.5'" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 1997". S 35° E Set nail and tag \$29245, North side fence post corner 9.72' N 88° W Set nail and tag \$29245, North side fence post corner 9.72' N 88° W Set nail and tag \$29245, North side fence post corner	NOTE: Not more than 4 corners, all in the same town and range, may be recorded	30	29	28	27	26	25	
Around 1825, H. Parke - Deputy Surveyor, "Set Post at aver. dist." and recorded two witnesses: "Y. Oak 28, S87°E, 81" (53.46") and "W. Oak 30, West, 43" (28.38"). Around 1888, H.F. Bean reported "post standing found remains of both witnesses. The section line is the South line of road". Also notes 2 witnesses: "Hickory 10, S1°W, 235" (155.10") and "W. Oak 2, N85 314°E, 57" (37.62"). A corner index card of Jackson County Road Commission (JCRC) reports "Fireclay post 24.80" South of centerline of Page Ave." and lists 4 witnesses: "16" Maple, N.35°W., 59.1; NW cor. House, S.37°W., 74.0; NE cor. House, S.22°W., 65.1; End fence Post, South, 33.0". In 1972, F.E. Spicer - RLS \$7877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: S85°W, Nail C/L CP/MBT pole, 20.85'; S15°W, NE cor conc bik fnd, 54.45'; N0°, S edge bikty pavt, 15'; N 45°W, Nail C/L 20" Maple, 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Keiter - RLS \$20707, recorded the corner as "Found capped Iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5'; S85°W, power pole, 20.80'; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of comer evidence found and/or method applied in restoring or reestablishing corner. Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 1997". S 35° E Set nail and tag \$29245, North side power pole 20.85' S 10° W Set nail and tag \$29245, North side power pole 20.85' S 10° W Set nail and tag \$29245, West side 8" tree 48.59' North Aspirate cent	A. Lessiphor of original monument and accessories and/or subsequent restoration.	31	32	33	34	. 3 5	36	
A corner index card of Jackson County Road Commission (JCRC) reports "Firectay post 24.80' South of centerline of Page Ave." and lists 4 witnesses: "16" Maple, N.35"W., 59.1; NW cor. House, S.37"W., 74.0; NE cor. House, S.22"W., 65.1; End fence Post, South, 33.0". In 1972, F.E. Spicer - RLS \$7877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: S85"W, Nail C/L CP/MBT pole, 20.85"; S15"W, NE cor conc bik fnd, 54.45"; N0°, S edge bikty pavt, 15"; N 45"W, Nail C/L 20" Maple. 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Keller - RLS \$20707, recorded the corner as "Found capped iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5"; S85"W, power pole, 20.80"; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and fastifful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 1997". S 35° E Set nail and tag \$29245, North side fence post corner 9.72' N 88' Set nail and tag \$29245, West side 8" tree 48.59' N 14° E Set nail and tag \$29245, West side 8" tree 48.59' N 14° E Set nail and tag \$29245, West side 8" tree 74.68' DAVID E. ERICKSON # ERICKSON	Around 1825, H. Parke - Deputy Surveyor, "Set Post at aver, dist" and recorded two witnesses. (IV. Oct. 20, 2077)							
Post, South, 33.0". In 1972, F.E. Spicer - RLS #7877, recorded the corner as "fire clay tile in lawn area" and lists 4 witnesses: S85°W, Nail C/L CP/MBT pole, 20.85'; S15°W, NE cor cone bik fnd, 54.45'; N0°, S edge biktp pavt, 15'; N 45°W, Nail C/L 20" Maple, 59.20" per Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Keller - RLS #20707, recorded the corner as "Found capped iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5'; S85°W, power pole, 20.80'; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (iP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4" diameter x 38" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 8" tree 4	Around 1888, H.F. Bean reported "post standing found remains of both witnesses. The section line is the South line of road". Also notes 2 witnesses: "Hickory 10, S1°W, 235" (155.10') and "W. Oak 2, N85 3/4°E, 57" (37.62').							
Land Corner Recordation Certificate (LCRC) recorded at Liber 1, Page 139. In 1979, R.W. Keller - RLS #20707, recorded the corner as "Found capped iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5"; S85°W, power pole, 20.80"; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' North Asphalt centerline 26.2' ERICKSON #ERICKSON ##ERICKSON #ERICKSON #ERICKSON ##ERICKSON	2744. GIAL HOLD 7 WILLIE 2003; "10" MIGDIE, N.32"YY., 29.1! NW COT, HOUSE S 379W 74 D. NE CAY LIAMOR C 22014/ CE 4. E							
In 1979, R.W. Keller - RLS #20707, recorded the corner as "Found capped iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5"; S85°W, power pole, 20.80"; S10°W, Northeast corner house, 54.5" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 210. B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (iP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4" diameter x 38" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' North Asphalt centerline 26.2' DAVID E. ERICKSON ##ERICKSON ###ERICKSON ###ERICKSON ###ERICKSON ###ERICKSON ###ERICKSON ###ERICKSON ####	OF/MID I POIR, 20.60°; 515°W, NE COT CONC DIK find, 54.45°; NO°, S edge blidte nave 45°. N 450W Marie Cot 300 Marie En 300 Marie							
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (iP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' DAVID E. BERICKSON # ERICKSON # Indeed to provide the power pole 26.2' DAVID E. BERICKSON # ERICKSON # Indeed to provide the power pole 26.2'	In 1979, R.W. Keller - RLS #20707, recorded the corner as "Found capped Iron & fireclay" and lists 3 witnesses: "north, centerline blacktop, 25.5'; S85'W, power pole, 20.80'; S10'W. Northeast corner house, 54.5'" reg. Land Corner Becombine							
Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (iP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS \$29245, 1997". S 35° E Set nail and tag \$29245, North side fence post corner 9.72' N 88° W Set nail and tag \$29245, South side power pole 20.85' S 01° W Set nail and tag \$29245, West side 8" tree 48.59' N 14° E Set nail and tag \$29245, West side 14" tree 74.68' North Asphalt centering and tag \$29245, West side 14" tree 26.2' DAVID E. ERICKSON AND A STANDARD	· •							
Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' North Asphalt centerline 26.2' ERICKSON 35° E Courts Suprement and 10 months 1	Found Fire Clay (FC) with pinch pipe on Southwest side and a 1" iron pipe (IP) on North side. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on West side of							
Set 4" diameter x 36" long concrete monument with cap stamped "H-3, T3S-R1E, LS #29245, 1997". S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' North Asphalt centerline 26.2' ERICKSON 35° E Courts Suprement and 10 months 1	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.							
N 88° W Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' S 01° W Set nail and tag #29245, West side 8" tree 48.59' N 14° E Set nail and tag #29245, West side 14" tree 74.68' North Asphalt centerline 26.2' ERICKSON ERICKSON ASPHALT SUMBOUR SIMBOUR S								
4) 18 6	North Asphalt centerline S 35° E Set nail and tag #29245, North side fence post corner 9.72' N 88° W Set nail and tag #29245, South side power pole 20.85' N 14° E Set nail and tag #29245, West side 8" tree North Asphalt centerline 28.2' ERICKSON ERICKSON And Supports size points							
Signed by Guel Guel Date 9-8-98 Surveyor's Michigan License No. 29245								