SURVEY & JACKSON COUNTY REMONUMENTATION APPROVED LAND CORNER P.A. 345 of 1990 EAST 1/4 POST, SECTION 14, LEONI TOWNSHIP MAR 1 3 2000 Chairman _A LAND CORNER RECORDATION CERTIFICATE Date 🖺 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in SECTION **JACKSON** Located in: Corner Code ≠ (County) R __ 1. Public Land Survey R 2126319 R Page: 1 of 2 R 08/11/1999 10:56A L-1609 P-418 2. Property Controlling Т ___ T S R in Section Miscellaneous S Т R Register of Deeds Stamp & File Number S _ T _ R Property in Sec. __ , Recorded Plat _ 5. Private Claims 3 AUGUST 26 ALAN L. SCHEPPELMAN I, ______, in a field survey on ______, 19 _____, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

HERVEY PARKE, D.S.

40.00 SET QUARTER SECTION POST

FEBRUARY 5, 1825

W. OAK 24, N23°E 7 LINKS (4.62')

S14°W 79 LINKS (52.14') Y. OAK 24,

HENRY F. BEAN

S22°E

expressed below:

POST AND ONE U.S. WITNESS STANDING. THIS CORNER

UNDATED HAS BEEN PRESERVED.

Y. OAK 16, N79°E 185 LINKS (122.10') HICKORY 12, S88°W 347% LINKS (229.35')

CONTINUED ON BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" PIPE IN MONUMENT BOX NEAR CENTERLINE OF INTERSECTION. EXCAVATED AND FOUND FIRECLAY WITH A SLEIGH SHOE ON THE EAST SIDE AT A DEPTH OF 3'±. THE SURFACE IRON WAS 0.06' EAST AND 0.03' SOUTH OF THE FIRECLAY LOCATION. ACCEPTED THE FIRECLAY AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. SET A 4" x 30" CAST IRON HARRISON MONUMENT AND BURIED THE FIRECLAY ON THE NORTH SIDE AND THE SLEIGH SHOE ON THE EAST SIDE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4" X 30" CAST IRON HARRISON MONUMENT WITH BRASS CAP STAMPED "K-6 T3S R1E LS 35998". Nllow SET NAIL & TAG 35998 IN THE EAST SIDE OF A 36" MAPLE 168.96' SET NAIL & TAG 35998 IN THE WEST SIDE OF A 24" OAK NO6°E

CENTERLINE OF SANITARY MANHOLE N06°W

SE CORNER OF PORCH FOUNDATION AT HOUSE #3951

SET NAIL & TAG 35998 IN THE EAST SIDE OF A TWIN 24" OAK SO4°W

SURVEY MARKER SIGN POST SASOW

06/04/99

Date: Signed by ... 3**4948** Surveyor's Michigan License No.

168.96 230.11 119.60 163.18 253.38 44.0 ALAN L. SCHEPPELMAN PROFESSIONAL SURVEYOR No. 35998 35998 35998 35998

10

11

12



2126319 Page: 2 of 2 08/11/1999 10:55A L-1609 P-418

PAGE 2

A. CONTINUED

K-6, T3S, R1E

CONSUMERS ENERGY FIELD BOOK #861 1958

FIRECLAY MONUMENT WITH SLEIGH SHOE ON THE EAST SIDE. S60°E 47.41' 36" ELM

30" MAPLE S15°E 88.85

TELEPHONE POLE S.W. 39.0'

SURVEY & REMONUMENTATION

JACKSON COUNTY ROAD COMMISSION MAY 24, 1962

IRON IN CENTER OF ROAD. 10" CEDAR N50°E 57.10' BELL POLE S45°W 38.85 BELL POLE S45°E 41.40' S50°E 46.00' 30" ELM

MAR 1 3 2000

SECTION

JOHN E. MAXSON RLS 27454 SEPTEMBER 13, 1988

LCRC - L. 4, P. 81 1/2" IRON PIPE IN MONUMENT BOX FORM NAIL IN 12" SPRUCE N26°W 101.78 FORM NAIL IN POWER POLE NB0°E 138.981

NW CORNER OF HOUSE SIDING S27°E 123.72' TOP CENTER OF TELEPHONE BOX \$44°W 44.50'

THESE SAME WITNESSES ARE ON A RECORDED SURVEY BY MAXSON, L. 1180, P. 1154, JACKSON COUNTY RECORDS.