SURVEY & JACKSON COUNTY REMONULARIATION APPROVED LAND CORNER P.A. 345 of 1990 East 1/4 Corner of Section 25, Napoleon Township JAN 2 7 1999 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 SECTION For corners in **JACKSON** Located In-Comer Code # 1. Public Land Survey M-10 2087040 Page: 1 of 99/18/1998 11 L-1580 P-5 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. Recorded Plat 5. Private Claims В C Ď F G F H 2 5 4 3 2 1 3 I. David E. Erickson, in a field survey on March 14 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established re-established monumented re-monumented recovered found as 7 8 Q 10 1.1 12 5 ó 18 17 16 15 14 13 7 Court of Law, established, re-established, monumented, re-monumented, recovered, found as 19 8 20 21 22 23 24 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 10 30 29 28 27 26 25 on this certificate. 11 12 Description of original monument and accessories and/or subsequent restoration: 31 32 33 34 35 36 In 1825, H. Parke - Deputy Surveyor, set a "Post" and recorded one witness: "W. Oak 12, S7°E, 300" (198.00') and "No other In the 1880's, a Remonumentation Surveyor reported "Old stone at corner agreeing with remains of Govt witness" and recorded two witnesses: "Y. Oak 12, S0 1/4°E, 248 1/2" (164.01') and "Poplar 10, \$44°E, 77 1/4" (50.98'). In 1972, R.E. Gutekunst - RLS #7863, recorded corner as "Found broken fire clay post & 1 1/2" x 1' solid bar. Set capped iron

In 1972, R.E. Gutekunst - RLS #7863, recorded comer as "Found broken fire clay post & 1 1/2" x 1' solid bar. Set capped iron on North side, 5.7' North of fence West & 4.7' West of fence South." and noted five witnesses: "S85°E, 10" Oak, 44.25'; S35°E, Dbl. Oak, 30.88'; South, 10" Oak, 38.7'; N85°W, 2" Oak, 33.3'; and South, 24" Oak, 171.33" " per Land Corner Recordation Certificate (LCRC) recorded in Liber 1, Page 411.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" x 5' long iron pipe (IP) up 0.7' with Fire Clay (FC) in 3 pieces, lying around IP. A 1" x 1/2" solid bar, 17" long is 0.1' West of IP. Found remains of 5" x 1.5' long wooden post, 1' deep. Accepted found IP as a careful and <u>faithful perpetuation</u> of the original corner. Replaced 1" IP with a standard concrete monument. Buried FC pieces on North side of monument.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer.

Set a 4" diameter x 36" long concrete monument with cap stamped "M-10, T3S-R1E, 1997, LS #29245".

N 76° W	Set nail & tag #29245, North side 9" Oak	33.44 [,]
S 73° E	Set nail & tag #29245, North side 14" Oak	18.74
S 25° E	Set nail & tag #29245, East side 17" Oak	16.40
S 44° W	Set nail & tag #29245, West side fence post	5.86'
South	County Surveyor sign post	0.8'

NOTE: Bearings are magnetic

DAVID E. ERICKSON Land Surveyor Williams Surveyor DAVID E. Land Surveyor Williams Surveyor Land Surv

Signed by tracel cuchs.

Surveyor's Michigan License No. 29245

9-8-98

Propagation of the same of the

PEVISED MAY 14, 1975 REVISED AAR , 1983

PEMBED JAN , 18 ADAPTED FOR WORD PROCESSING NARCH, 19