JACKSON COUNTY SURVEY & APPROVED LAND CORNER P.A. 345) of 1990 REMONUMENTATION South 1/4 Corner of Section 30, Summit Township LAND CORNER RECORDATION CERTIFICATE JAN 27 1999 1998 Date 0697 Filing Requirement of Act 74, Mich. P.A. 1970 For comers in SECTION **JACKSON** Located In: Corner Code # 1. Public Land Survey T3S R1W 2087045 B-11 Page: 1 of 1 09/10/1998 11:5 L-1580 P-52 2. Property Controlling in Section Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 8 С D F G н JK LI 2 6 5 3 2 3 1, <u>David E. Erickson</u>, in a field survey on <u>February 10</u> 19 <u>97</u>.

do heraby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 4 7 8 Q 10 31 5 current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: ó 18 17 16 15 14 7 19 8 20 21 22 23 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 10 30 29 28 27 26 25 11 Description of original monument and accessories and/or subsequent restoration: 12 31 32 33 34 35 36 In 1825, H. Parke - Deputy Surveyor, set a "Post" and recorded two witness: "W. Oak 12, N25°E, 65 1/2" (43.23') and "Hick 14, S7 1/2°W, 95" (62,70'). Around 1886, H.F. Bean reported "Found remains of Post & Witnesses" and recorded two witnesses: "Y. Oak 2, N39°W, 10 1/2" (6.93') and "W. Oak 10, S2 1/2°E, 49" (32.34'). In 1980, R.W. Keller - RLS #20707, recorded the corner as "Found Fire Clay" and lists 4 witnesses: "N5°W, 24" Cherry, 26.32'; East, 10" Cherry, 23.67'; North, 48" Cherry, 56.35'; S85°E, 15" Cherry, 29.30" per Land Corner Recordation Certificate (LCRC) recorded at Liber 3, Page 302. Description of comer evidence found and/or method applied in restoring or reestablishing comer: Found Fire Clay (FC) with 1" galvanized Iron Pipe (IP) on South side neaffence intersection. Also found pottery pieces below FC. Accepted found FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on South side of monument. Description of monument for comer and accessories established to perpetuate locating the position of the comer: Set 4" diameter x 36" long concrete monument with cap stamped "B-11, T3S-R1W, LS #29245, 1997". N 10° W Set nail and tag #29245, East side 38" Oak 57.18 N 73° E Set nail and tag #29245, North side 48" Cherry 28.32 N 17° E Set nail and tag #29245, Northwest side 8" Oak OF MICHIGAN 31.83 N 50° W Set nail and tag #29245, Southwest side 6" Oak 8.91 S 52° E Steel fence post 1.5 Northeast County Surveyor sign post 2.0 South East-West fence line DAVID E 2.0 East North-South fence line **ERICKSON** 1.5 Land Surveyo 29245 LAND SURVE NOTE: Bearings are magnetic 9-8-98 Signed by

Surveyor's Michigan License No.

1

12

13

24