/FUROVED LAND COUNTY P.A. 345 of 1900	SOUTH \$\frac{1}{4}\$ POST, SECTION SUMMIT TOWNSHIP/CITY OF	ON 4 P JACKSON COMMON TO SECOND	
Circination Co.	LAND CORNER RECORDATION	CERTIFICATE	#2029644
FIGURET B. UMO CON	Filing Requirement of Act 74, I		Liber 1538 Page 540
For corners in	Filing Requirement of Act 74, i	viich, P.A. 1970	Page 1 of 2
		h	Jackson Co., MI
	cated In: Corner Code =	#SURVEY &	Recorded
(County)	REN	ONUMENTATION	03/13/97 03:42P
1 Dublin Land Survey T	35 R 1 W F-3	į	Mindy Reilly
•	R	APR 0 7 1998	Resister of Deeds
	n	APR	Kearatet of peeds
	R		
		SECTION	
· •	R		
	R		
	`R	Register of Dee	ds Stamp & File Number
Property in Sec. S T	R		
4. Lot No, Recorded Plat		A B C	DEFGHIJKLI
5. Private Claims			
J. 111010 June 1		2 - 6	\$
		3	
		4 1	
Dean R. Gutekunst in a field su	August 7	19 96	
in a field su			
do hereby certily that under requirements of P	.A. 74, Michigan F.A. 011970, the corner politically regulations, and sules therefore as st	equired to the	17-16-15-14-13-
in lines 1 and 2 above were in conformance current manual of survey instructions of the t	Inited States Department of the Interior B	ureau of Land	} }
Management or by a decree of a Court of Law a	and/or that the corner points mentioned in I	ines 3, 4 and 5 8	20 21 22 23 24
above were in conformance with the rules of t	he Michigan Board of Land Surveyors or by	a Decree of a	
Court of Law; established, re-established,	monumented, re-monumented, recover-	ed, found as	
expressed below:		10 30	29 26 27 26 25
NOTE: Not more than 4 corners, all in	the same town and range, may be re	corded 11	╎╎┤┤╏ ╇╇╇╇
on this certificate.		12	32 33 34 35 36
		13	
A. Description of original monument an	id accessories and/or subsequent res	toration:	
Oni sine I Concemment Post	set by Hervey Parke, Depu	ty Surveyor, 1825.	
W. Oak 12" N 66 W	41 links (27.06')		
N. URK IZ I OU "			
	* 63 14nks (41.58°)		
W. Oak 26" N 83½ E	63 links (41.58')	Post and 2	witnesses standing.
W. Oak 26" N 83½ E	ean. 1886	Post and 2	witnesses standing.
W. Oak 26" N 83½ E	ean. 1886	Post and 2	witnesses standing.
W. Oak 26" N 83½ E	ean. 1886	Post and 2	witnesses standing.
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E	ean. 1886	Post and 2	witnesses standing.
W. Oak 26" N 83½ E	ean. 1886	Post and 2	DEAN R.
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E	ean. 1886	Post and 2	DEAN GUTEKUNST
W. Oak 26" N 83 $\frac{1}{2}$ E Perpetuation by H. F. Be W. Oak 22" N $66\frac{1}{2}$ W. Oak 36" N $3\frac{1}{2}$ E Continued on back,	ean, 1886. 1 40 links (26.40') 2 96½ links (63.69')		DEAN R.
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E	ean, 1886. 1 40 links (26.40') 2 96½ links (63.69')		DEAN R. GUTEKUNST No. 18658
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring		DEAN GUTEKUNST
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring an concrete.		DEAN R. GUTEKUNST No. 18658
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron.	or reestablishing comer:	DEAN R. GUTEKUNST No. 18658
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under 1	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of	or reestablishing corner:	DEAN R. GUTEKUNST No. 18658 AND LAND
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the concret. Area is mostly a	or reestablishing comer:	DEAN R. GUTEKUNST No. 18658 AND LAND
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under 1	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the concret. Area is mostly a	or reestablishing corner:	DEAN R. GUTEKUNST No. 18658 AND LAND
W. Oak 26" N 83½ H Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ H Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the concrete. Area is mostly attion.	or reestablishing corner: 1 4', did not reveal sand fill from former	DEAN GUTEKUNST No. 18658 Any additional sewer
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersect Accepted iron rods as a	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to a concrete. tion. careful and faithful perpendicular to a concrete.	or reestablishing corner: f 4', did not reveal sand fill from former estuation of the posit	DEAN GUTEKUNST No. 18658 Any additional sewer
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersect Accepted iron rods as a	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to a concrete. tion. careful and faithful perpendicular to a concrete.	or reestablishing corner: f 4', did not reveal sand fill from former estuation of the posit	DEAN GUTEKUNST No. 18658 Any additional sewer
W. Oak 26" N 83½ H Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ H Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the concrete. tion. careful and faithful perpendicularity is concurred by F. C. Riley in	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit	DEAN R. GUTEKUNST No. 18658 any additional sewer ion of the
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem Set a Standard Jackson	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the restoring to the rons. Area is mostly to the restoring t	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit	DEAN R. GUTEKUNST No. 18658 any additional sewer ion of the
W. Oak 26" N 83½ H Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ H Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the restoring to the rons. Area is mostly to the restoring t	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit	DEAN R. GUTEKUNST No. 18658 any additional sewer ion of the
W. Oak 26" N 83½ H Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ H Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument and iron	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of rier. Area is mostly a tion. careful and faithful perponumented by F. C. Riley in County Monument to replace rods around monument.	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and pl	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete
W. Oak 26" N 83½ H Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ H Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument and iron	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of rier. Area is mostly a tion. careful and faithful perponumented by F. C. Riley in County Monument to replace rods around monument.	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and pl	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the restoring to the rons. Area is mostly to the restoring to the rons and box, to a depth of the restoring to	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit n 1931. the iron rods and pl	DEAN R GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner:
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co excavations in intersec Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner C. Description of monument for corner	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of mer. Area is mostly into a careful and faithful perpendicularly for the control of the	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit n 1931. the iron rods and pl	DEAN R. GUTEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36"
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. W. Oak 36" N 3½ Fermion of corner evidence found 5/8" rod in box in the second and a rod below hand excavation under intersect the second and intersect the second and second and intersect the second and inters	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of rier. Area is mostly in the concrete is a faithful perpendicular to replace irons. County Monument to replace irods around monument. and accessories established to perpendicular is a 4" diameter X 36" and and an aluminum cap	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and placetuate locating the position of concrete monument wis stamped IS 18658, who	DEAN R. GUTEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36"
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the rons. Area is mostly to the restoring to the rons. careful and faithful perpendicular to replace to the rods around monument. and accessories established to perpendicular and an aluminum capundard monument for Jackson	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the rons. Area is mostly to the restoring to the rons. careful and faithful perpendicular to replace to the rods around monument. and accessories established to perpendicular and an aluminum capundard monument for Jackson	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the rons. Area is mostly to the restoring to the rons. careful and faithful perpendicular to replace to the rods around monument. and accessories established to perpendicular and an aluminum capundard monument for Jackson	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the rons. Area is mostly to the restoring to the rons. careful and faithful perpendicular to replace to the rods around monument. and accessories established to perpendicular and an aluminum capundard monument for Jackson	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the rons. Area is mostly to the restoring to the rons. careful and faithful perpendicular to replace to the rods around monument. and accessories established to perpendicular and an aluminum capundard monument for Jackson	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn ste * N 35° E Doub N 86° E Doub	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the restoring in the restoring in the rons and box, to a depth of the restoring in the rons and box, to a depth of the restoring in the rons and box, to a depth of the restoring in the rons and sound faithful perpendicularly Monument to replace rods around monument to replace rods around monument. and accessories established to perpendent is a 4" diameter X 36" and an aluminum cap indard monument for Jackson the 21" Walnut 143.94' the (12" & 15") Oak 150 Pine 85.82' Oak 104.53'	or reestablishing corner: 2 4', did not reveal sand fill from former etuation of the position of the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county. 40d & washer on	DEAN GUIEKUNST No. 18658 No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. on South side of 12". South side. South side.
W. Oak 26" N 83½ E Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ E Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument and iron C. Description of monument for corner F-3 T3S, RIW Corner * N 35° E Doub N 86° E Doub	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring to a concrete. surface iron. rons and box, to a depth of the restoring to the restoring to the rons. Area is mostly to the restoring to the restoring to the restoring to the rons. careful and faithful perpetent to the restoring to the	or reestablishing corner: 9 4', did not reveal sand fill from former etuation of the position 1931. the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county.	DEAN GUIEKUNST No. 18658 No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. on South side of 12". South side. South side.
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. W. Oak 36" N 3½ Fermion of corner evidence found 5/8" rod in box in the second and a rod below hand excavation under intersect the second and intersect the sec	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of mer. Area is mostly into a strong in contrect in the constant	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit n 1931. the iron rods and pl stuate locating the position of concrete monument wi stamped IS 18658, wh County. 40d & washer on	DEAN R. GUIEKUNST No. 18658 AND THE SEWER ION of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. In South side of 12". South side. East side.
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. W. Oak 36" N 3½ Fermion of corner evidence found 5/8" rod in box in the second and a rod below hand excavation under intersect the second and intersect the sec	ean, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the restoring in the restoring in the rons and box, to a depth of the restoring in the rons and box, to a depth of the restoring in the rons and box, to a depth of the restoring in the rons and sound faithful perpendicularly Monument to replace rods around monument to replace rods around monument. and accessories established to perpendent is a 4" diameter X 36" and an aluminum cap indard monument for Jackson the 21" Walnut 143.94' the (12" & 15") Oak 150 Pine 85.82' Oak 104.53'	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit n 1931. the iron rods and pl stuate locating the position of concrete monument wi stamped IS 18658, wh County. 40d & washer on	DEAN R. GUIEKUNST No. 18658 AND THE SEWER ION of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. In South side of 12". South side. East side.
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. W. Oak 36" N 3½ Fermion of corner evidence found 5/8" rod in box in the second and a rod below hand excavation under intersect the second and intersect the sec	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the restoring in the restoring in the restoring in concrete. careful and faithful perpendicular and faithful perpendicular and faithful perpendicular and accessories established to perpendicular and accessories established to perpendicular and and an aluminum capundard monument for Jackson in the 21" Walnut 143.94' the (12" & 15") Oak 150 Pine 85.82' Oak 104.53' Oak 144.18' et over monument by Jackson	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position of the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county. 40d & washer on 60d & washer	any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. South side of 12". South side. South side. East side. on.
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. W. Oak 36" N 3½ Fermeture of the W. Oak 36" N 3½ Fermeture of the W. Oak 36" N 3½ Fermeture of the W. Oak 36" rod in box in the Widence of original content of the Widence of original content of the Widence of the W	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the restoring in the restoring in the restoring in concrete. careful and faithful perpendicular and faithful perpendicular and faithful perpendicular and accessories established to perpendicular and accessories established to perpendicular and and an aluminum capundard monument for Jackson in the 21" Walnut 143.94' the (12" & 15") Oak 150 Pine 85.82' Oak 104.53' Oak 144.18' et over monument by Jackson	or reestablishing corner: f 4', did not reveal sand fill from former etuation of the posit n 1931. the iron rods and pl stuate locating the position of concrete monument wi stamped IS 18658, wh County. 40d & washer on	DEAN GUIEKUNST No. 18658 No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. on South side of 12". South side. East side. on.
W. Oak 26" N 83½ Ferpetuation by H. F. Be W. Oak 22" N 66½ W. Oak 36" N 3½ Fe Continued on back, B. Description of corner evidence found 5/8" rod in box in Also found a rod below Hand excavation under it evidence of original convex avations in intersect Accepted iron rods as a consignal corner, as remused as a second below monument and iron contents. C. Description of monument for corner F-3 T3S, RIW Corner stems at a standard Jackson below monument and iron the second stems at a standard Jackson below monument to corner from the second standard Jackson below to the second standard Jackson below to the second standard Jackson below to the secon	an, 1886. 40 links (26.40') 5 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of mer. Area is mostly into a strong in conting in the con	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position of the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county. 40d & washer on 60d & washer 60d &	DEAN GUIEKUNST No. 18658 No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. In South side of 12". South side. South side. East side. on. 997
W. Oak 26" N 83½ F Perpetuation by H. F. Be W. Oak 22" N 66½ W W. Oak 36" N 3½ F Continued on back, B. Description of corner evidence foun Found 5/8" rod in box i Also found a rod below Hand excavation under i evidence of original co- excavations in intersect Accepted iron rods as a original corner, as rem Set a Standard Jackson below monument for corner F-3 T3S, RIW Corn C. Description of monument for corner F-3 T3S, RIW Corn ste * N 35° E Doub N 86° E Doub	ean, 1886. 40 links (26.40') 96½ links (63.69') d and/or method applied in restoring in concrete. surface iron. rons and box, to a depth of the restoring in the restoring in the restoring in concrete. careful and faithful perpendicular and faithful perpendicular and faithful perpendicular and accessories established to perpendicular and accessories established to perpendicular and and an aluminum capundard monument for Jackson in the 21" Walnut 143.94' the (12" & 15") Oak 150 Pine 85.82' Oak 104.53' Oak 144.18' et over monument by Jackson	or reestablishing corner: P 4', did not reveal sand fill from former etuation of the position of the iron rods and plantate locating the position of concrete monument wistamped IS 18658, who county. 40d & washer on 60d & washer 60d &	DEAN GUIEKUNST No. 18658 No. 18658 any additional sewer ion of the aced broken concrete the corner: th a ½" X 36" ich is the Southeast side. on South side of 12". South side. East side. on.

Continued,

F-3 T3S, R1W

A. - Perpetuation by F. C. Riley, #377, 1931.

* Double Walnut N 34 E 142.32' Iron Walnut 16" East 160.49' Cherry 10" N 41 30 W 92.50'

- Perpetuation by the Jackson County Road Commission, no name, no date.

Iron 1' deep 12" Box Elder S 40 E 204.4' 14" Ash S 89 E 160.5'

12" Ash N 10 30 W 124.7'

- Perpetuation by Richard E. Gutekunst, RIS # 7863, January 13, 1978.

Found iron in monument box

** S 60 W 12" Pine 85.87'

*** N 60 W 15" Oak 104.56'

N 25 W 10" White Oak 114.35'

N 30 E 14" Oak 76.02'

- Not recorded in P.A 74.