JACKSON COUNTY PPROVED LAND CORNER P.A. 345 of 1990

For

SOUTHWEST CORNER SECTION 2 GRASS LAKE TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

corners in JACKSON	Located In:	Corner Code ##	#0000010			
(County)		SURVEY &	#2028010			
Public Land Survey	7 3 S R 2 E	1-3 REMONUMENTATION	Liber 1537 Page 31 Page 1 of 1 Jackson Co., MI			
	T R	ΔPR 0 7 1998	Recorded 02/21/97 08:38A			
Property Controlling in Section	S T R S T R	SECTION	Mindy Reilly Register of Deeds			
Miscellaneous	S T R		Register of Deeds Stamp & File Number			

Property in Sec. \_\_\_ , Recorded Plat 4. Lot No. 5. Private Claims

7/27/94 & 11/21/95 Dean R. Gutekunst in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 12

DEAN

**GUTEKUNST** 

No. 1865

CHED LAND

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Post set by Hervey Parke, Deputy Surveyor, February 1824. White Oak 16" S 14½ E 37 links (24.42' White Oak 12" N 9 37 links (24.42')

Not recorded in P. A. 74

No perpetuation found for the 1880's.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 3/4" X 22" iron pipe to the gravel surface of Barber Road, 7/27/1994.

Excavated a 20' X 20' X 4' deep hole, with a backhoe, centered around the iron, but found nothing additional.

Corner is 1.5' West of the center line of the blacktop and 1.5' North of a fence West and 3.5 't North of a fence East.

Accepted surface iron found as the only perpetuation of the position of the original corner.

Set a Standard Jackson County Monument to replace the iron and left iron buried beside monument, 11/21/1995.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>I-3 T3S</u>	, R2E Corn	er is a 4"	diameter	X 36" concrete	monument with a $\frac{1}{2}$	" y 36"
	stee	l rod and a	an alumin	um cap stamped L	S 18658, which is	the standard
	monu	ment for Ja	ackson Co	unty.		
и 30° Е	18" Hickory			Od on Southeast	side	
East	12" Pine	35.481	40d & w	asher on South s	ide	
S 85° Е				40d & washer on		
s 30° w	Utility Pole	50.08'	40d & w	asher on South S	outheast side	
s 45° w	24" Oak	41.03	Found 6	Od on Southeast	side	
s 60° w			Found	60d on South Sou	theast side	
N 500 H	24" Cak	30.82'	Found	60d on Southwest	side	
<b>West</b>	Steel post and	survey mar	ker sign	attached 25	.01	
Monument box	k set ovez monu	menta by Jac	kson Cou	nty Road Commiss:	ion	
igned by	all the	= /		Date	Februar	y 1, 1997
igned byurveyor's Michigan Lic	186	58				
urveyor's Michigan Lic	ense No					

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14 1975