JACKSON COUNTY APPROVED LAND CORNER

SURVEY & REMONUMENTATION

P.A. 343 of 1990	-A			APR 2 8 1998
Chairman Nov. 12, 1997	NORTHEAST CORI	NER, SECTION 14, SPR	ING ARBOR TWP.	. HLK & 0 1998
For corners in	Filing Requ	IER RECORDATION CE irement of Act 74, Mich	RTIFICATE a. P.A. 1970	SECTION 42053:275
Jackson	Located In:	Corner Code #		Liber 1555 Page 7
(County)	Located III.	Collies Code #		Jackson Co., MI
1. Public Land Survey	T <u>3S</u> R <u>2W</u> TR	K-5		'
	TR		Q.	Minda Reilla Resister of Deeds
2. Property Controlling S in Section S	TR TR TR	leg.#2	.,	
3. Miscellaneous S	TR			
Property in Sec. S	/R		Registe	r of Deeds Stamp & File Number
4. Lot No, Recorded P	riat			
5. Private Claims			1 A B C	DEFGHIJKL
			2 6	-5 - 4 - 3 - 2 - 1
I, Michael A. Groat in a field under requirements of P.A. 74, Michigan P	A. of 1970, the corner points	ede C bee b coali ai boaciteem:		0 9 10 11 12
the United States Department of the Interior	therefore as required in the o	current manual of survey instruction by a decree of a Court of L	tions of	17-16-15-14-12
for that the corner points mentioned in lik Michigan Board of Land Surveyors or by a C recovered, found as expressed below:	nes 3. 4 and 5 above were	in conformance with the rules	of the	
NOTE: Not more than 2 corners, all	in the same tour and an		8 - 19	-20 -21 -22 -23 -24
on this certificate.	in die same fown aud lai	nge, may be recorded	10-30-	-29 20 272625
			11	32 33 34 35 36
			12 31-	-3233343536
 A. Description of original monument 		•		
Original Survey by Lucius Lyon, depu Links; Br. Oak, 16", S64°E, 15 Links	ıty surveyor in 1825, set	post, W. Oak, 30" N61°W	, 108	
H.F. Bean, 1886, Found part of post a Links.	and 2 witnesses standing	g, set fireclay tile; Y. Oak, 2	28", N11°W, 227 Link	s; W. Oak, 20", S24°W, 85½
Consumers Power Co. witnesses stat S20°W, 71.4'; Corner post, East, 26.0	e that a iron was found J'; S25°W, 24″ Oak, 77.	In a monument box in line t 52'.	with a fence East; 6" I	Birch, S50°W, 56.8'; 20" Oak,
Duane Ankrom, P.S. #21265, in 1992 16" Elm, S20°W, 77.54', 36" Oak.	, found a uncapped re-b	ar in a monument box. N4	5°E, 33.32', P.P.; N6	0°E, 48.15', P.P., \$45°E, 44.8(
3. Description of corner evidence fo	und and/or method appl	led in restoring or reestabil	shing corner:	
Found monument box in centerline of ireclay. Accepted the position of the foundation of the foundation in place of the tile.	North and South road w fireclay as a careful and	ith 1/2" iron inside. Dug ar faithful perpetuation of the	nd at 2' down, square original corner set by	steel rod and at 2.5' found Lyon. Set a 4"x36" concrete
Description of monument for corne	er and accessories estab	lished to perpetuate locatin	a the position of the a	corner:
he corner is a standard Jackson Cou ap.				
Vitnesses:				
50°E Nail and tag in Southeasterl 55°W Nail and tag in Southerly sig	le of utility pole	36.91 ' 48.10'		
80°E Nail and tag in Southerly side 20°W Nail and tag in Easterly side	le of fence post of 20" Oak	26.98 ' 76.60'		
60°W Face of Stop sign post ast Survey marker sign		31.91' 26. <i>75</i> '		
,	TE OF MICHIGAN			
gned by 746 (1)	MICHAELA LA TA	Da	ate <u>November 11</u>	_ 1997
11 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 	079GNOAT			
\$ 6 1	SURVEYOR OF			
15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	No. 39679	FORM APPROVED	SY MICHIGAN STATE BOARD O	f professional surveyors, Jan. 28, 1: Revised Jan., 1
The state of the s	OFESSIONAL			REVISED OCT.