JACKSON COUNTY APPROVED LAND CORNER SOUTHEAST CORNER, SECTION 10 CONCORD TOWNSHIP SURVEY & REVION MENTATION LAND CORNER RECORDATION CERTIFICATE 8-98 Filing Requirement of Act 74, Mich. P.A. 1970 SEP 1 6 1998 For corners in JACKSON Located In: Corner Code ## (County) SECTION T<u>38</u>R3₩ 1. Public Land Survey 2080956 Page: 1 of 2 T _ R 07/21/1998 10:30A **Property Controlling** R L-1575 P-1167 in Section S T Я Miscellaneous S T . A ... Register of Deeds Stamp & File Number Property in Sec. _ R _ , Recorded Plat 5. Private Claims DEAN R. CUTEKUNST _ , 19 **9**7 September , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Lucius Lyon, Deputy Surveyor, April 1825. Br. Oak 11" N 2 E 16 links (10.56') 9" Br. Oak S 24 E 52 links (34.52') Perpetuation - No name - No date. Found Red Cedar stake and Crocker *Br. Oak 24" N 55 W 66 links (43.56') ("sd those been kept 50 years") 30" S 65 E Br. Oak $79\frac{1}{2}$ links (52.47') Continued on back. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" solid rod on North side of bar. Found $\frac{1}{4}$ " rod and $\frac{1}{2}$ " pinched iron on West side of bar in monument box. Backhoe excavation of the area, by the Jackson County Road Commission, found 3/4" bar and broken brick and crockery, 3.65' below surface. Reset 3/4" bar, broken brick Reset 3/4" bar, broken brick, crockery and glass, 4't below surface. Corner is 1' East of center line of North Concord Road (blacktop) and 1' North of center line of King Road running West (blacktop) and 3' + North of cneter line of King Road running East. Accepted 3/4" bar, brick and crockery as a careful and faithful perpetuation of the position of the original corner, as remonumented by Bean. Set a Standard Jackson County Monument to replace the 3/4" bar and left bar buried below monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: T3S, R3W Corner is a 4" diameter X 36 concrete monument with a 3" X 36" steel rod and an aluminum cap stamped LS 18658, which is a standard monument for Jackson County. 46" 0ak 109.20' N 15 E Pole barn spike and washer on Southeast side. 36" Oak 133.40' S 20 E Pole barn spike and washer on West side. S 80 W 25" Oak 171.08' .08' Pole barn spike and washer on South side. 119.6' No nail (blaze on South side). 8" Hickory N 75 E

GUTEKUNST

East Southeast corner concrete foundation of house

Monument box set over monument by Jackson County Road Commission.

N 45 W

Continued,

- A.) Perpetuation by H. F. Bean, no date.

 *Br. Oak 28" N 56 W 65½ links (43.23')

 Br. Oak 4" S 18 W 111½ links (73.59')
 - Perpetuation by Jackson County Road Commission, R. M. Davis, 1921.

 ** Br. Oak 28" N 15 E 108.4" Set 3/4" Bar

 Br. Oak 12" S 19 10 W 54.0'

 * Br. Oak 30" N 55 45 W 43.2"
 - P. A. 74, recorded by Richard E. Gutekunst, RLS #7863, dated October 18, 1972, in LCRC, Liber 1, Page 613, Jackson County Records.

Found monument box with #" rod inside.

** N 20 E 40" Oak 109.4'
N 70 W 24" Maple 133.8'
*** S 10 E 26" Oak 133.68'

Mindy Rellly - Jackson Co. CORREM

2080955 Page: 2 of 2 07/21/1980 10:30A L-1575 P-1167

SURVEY & REMONUMENTATION

SEP 1 6 1998

SECTION