APPROVED LAND CORNER P.A. 345 of 1990 Chairman Daul E. Eules	north ‡ Post Norvell Towns	SECTION 4 SHIP		
Date NOU. 18.1998	LAND CORNER	RECORDATION CERTIF	ICATE	
For corners in	Filing Requirer	ment of Act 74, Mich. P.A	. 1970	
JACKSON		i		
(Gounty)	Located in:	Corner Code ##		
	_•	F-1		
Public Land Survey	T <u>4 5 R 2 E</u> TR		Main 23000 Mari III 5910 MI (201 2099414	
	T R		Page: 1 of 2	
	T R		12/23/1998 11:22A L-1589 P-646	
	<u>T</u> <u>B</u>	Mindy Reilly - Jac	okson Co. CORREM L-1368	
	T A T A			
			Register of Deeds Stamp & File Number	
· ·				
4. Lot No, Recorded 5. Private Claims			A B C D E E G H I J K L M	
5. Private Claims			2 6 4 5 4 4 3 4 2 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1 4 1	
			3	
DEAN R CHTEKINST	Sept	ember 25 97	4 - 7 - 1 - 8 - 1 - 9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
DEAN R GUTEKUNST in a field survey on September 25 , 19 97 5 7 8 9 10 11 12 12 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15				
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawland/or that the corner points mentioned in lines 3, 4 and 5				
above were in conformance with the rule	-			
Court of Law; established, re-established expressed below:	snea, monumentea, re-ma	onumentea, recoverea, touna	as 10 30 29 28 27 26 25	
NOTE: Not more than 4 corners, a	all in the same town and	I range, may be recorded	11	
on this certificate.		•	12 31 32 34 35 36	
A. Description of original monume	of and accessories and/	or subsequent restoration:	13	
Corner not set in or:				
	_	-		
•	3½ E 45 links (29.7')		
	Northwest corner	and Northeast corner	, on December 15, 1973, of Section 4 and on line of RZE. Set 3/4" X 15" capped iron	
Continued on back,				
B. Description of corner evidence	found and/or method ap	plied in restoring or reestab	lishing corner:	
Found iron in blackte	op from above inf	ormation.		
Backhoe excavation of appears to have been			nal information. Road	
occupation North or	South .		on Valley Road) and there is no	
Accepted iron and me	thod of establish	ment as the best pos	ition of this corner of michigan	
Accepted iron and method of establishment as the best position of this corner of the c				
	•	_	★	
			GUTEKUNST SEE	
	•		100.1000	
C. Description of monument for co	orner and accessories es	tablished to perpetuate loca	ating the position of the comercy	
F-1 T4S RZE	Corner is a 4" d	iameter X 30" Cast I	ron Harrison monument With a	
	Brais cap stampo Jackson County.	d LS 18658, which is	a standard monument for	
N 20 W 8" Maple		barn spike and washe		
N 80 W 3- 24" Oak	N 80 W 3- 24" Cak 124.34' Pole barn spike and washer on South side. S 55 W 16" Fin 64.74' Pole barn spike and washer on North side.			
5 70 E 7" Oak				
West South # Post of Section 33, T35,R2E (Harrison Monument) 243.62'				
South Steel post a Monument box set over			8.4'* mission.	
ul/o. A	// 1/ 1)	<u>,</u>	November 1, 1998	
Signed by	18658	Date		
Surveyor's Michigan License No.	<u> </u>		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1985	

Continued,

12" Hickory 32.58'
18" Oak 39.28'
Northeast corner of foundation house #11523 131.78'
South † Post of Section 33, T3S, R2E 243.53' (fireclay) N 5 B N 45 W S 45 W West A.)

- Not recorded in P. A. 74

2099414 Page: 2 of 2 12/23/1996 11:228 L-1589 P-646