PARTE STATE

REMONUMENTATION

Che's ma Ken K	LAND C	ORNER RECORDATI			MAR 1	3 2000	
Bate Fes. 10,19	Filing R	equirement of Act 74	l, Mich. P.A. 19	70	SECT	'ION	
For corners in JACKSON (County)	Located In:	Corner Code #					
1. Public Land Survey	T <u>4S</u> R <u>2W</u> T R T R T R	A4	ey Relliy - Jackson		GORREM	2104470 Page: 1 o 02/10/1999 L-1593 F	10:51A
Property Controlling in Section Miscellaneous Property in Sec.	\$TR_ \$TR \$TR \$TR	Mir			eds Stamp		
4. Lot No, Record 5. Private Claims	ded Plat		<u> </u>	A B	C D E F	C H t J	K L N
				2 6	5 4	9 2	
r. David E. Erickson, in	a field survey on May 1	5	, 19 <u>98 ,</u>	4 7	8 0	10 11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						13	
above were in conformance with Court of Law; established, expressed below:	h the rules of the Michigan Bo	erd of Land Surveyors or by a	Decree of a	8 19	20 2)	22 23	24
NOTE: Not more than 4 con this certificate.	orners, all in the same tow	n and range, may be recor	deđ	10 30	29 28	27 26	25
A. Description of origin	al monument and acces	sories and/or subsequen	it restoration:	12 31	32 33	34 35	36

This corner not set in original government survey.

In 1980, R.W.Keller, RLS #20707, recorded the corner in a Land Corner Recordation Certificate (LCRC) at Liber 3, Page 304, as "found capped iron 3' West of centerline road" and recorded 5 witnesses: N30°E, 30" Catalpa, 54.45'; N70°E, 15" Catalpa, 35.58'; S45°E, 24" Maple, 33.05'; N80°W, 10" Cherry, 30.80'; North, Iron, 138.50'.

В Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" rebar at surface (Keller's). Excavated large area, 4' deep with backhoe, 8' North, 10' South, 5' West, 3' East, of rebar. Nothing else found below rebar. Found an older 1/2" x 18' iron with an old 4" x 7" flat piece of iron alongside, 0.7' deep. The 1/2" iron is SW, 0.31' from the single proportionate location. The flat iron was on the North side, lying horizontal. Re-established this corner by single proportion, which is essentially the same position as the flat iron. I feel the flat iron may have been set for the corner long ago, possibly disturbed, with the 1/2" iron set later, alongside. Set a standard Jackson County Harrison Cast Iron Monument, midway between remonumented corners A-3 and A-5, and on the Township line. Rejected the surface iron as recorded by Keller. Buried the three irons on the North side of the monument.

Description of monument for comer and accessories established to perpetuate locating the position of the corner:

Set standard Jackson County Harrison Cast Iron Monument, stamped "A-4, #29245".

N20°E	Set Nail & Tag #29245 in Southwest side 18" Cedar	93.59'
575°E	Northwest corner foundation to house #8505	76,11
\$16°W	Set Nail & Tag #29245 in East side 18" Hickory	87.17'
N66°W	Set Nail & Tag #29245 in South side 20" Walnut	38.72
S42°E	Iron per Liber 3, Page 304 (not reset)	2,94'
West	County Surveyor sign post	18.0'
North	Corner M-4, T4S-R3W, Harrison monument	134,71
North	Corner A-3, T4S-R2W, Harrison monument	2644.41"
North	Corner A-5, T48-R2W, Harrison monument	2644.41'
Note: Bes	ringe are magnetic	



Note: Bearings are magnetic.	LAND SUR
Ser bar	2-9-99
Signed by land curtifun	Date Q J J J
Surveyor's Michigan License No. 29245	FORM APPROVED BY INCIDENT STAYE BOARD OF LAVID SUBJECTION OF LAVID SO - 4474