ICHECOS CONTRA INDICIONA NAMA CONTRA INA. 898 OF SAA	A >									
North 1/4 Corner of Section 14, Hanover Towns					•	#2064448				
13000 Mac. 11, 1998	LANI	CORNER RECORDA	TION CERTII	FICATE			Libe	er 156		e 994
The state of the s	Filing	Requirement of Act 74	i, Mich. P.A. 1	970				: 1 (son (
For corners in								onded	<i>.</i> 0.5 f	!1
JACKSON Loca (County)	ated In:	Corner Code #					93/0	2/199		00P
4. Diship I and Owner	Ten Dow							ia Kei		
Public Land Survey	T <u>4S_R2W</u> TR TR_R	SU RVEY & EMON <u>UMENT</u> AT	TION				reg)	ster	or ve	eds
2. Property Controlling S	_ TR									
in Section S 3. Miscellaneous S	_ T R	SEP 1 6 1998								
Property in Sec. S	_ † <u>;;</u>	<u> </u>	}	Regist	er of De	eds St	amp 8	. File N	lumbe	:r
4. Lot No, Recorded Pla	at	SECTION	<u> </u>							
5. Private Claims				1	A B	C D	E F (3 H I	1 K	L M
				2	- 6-	5	4	3	2	1
				3	1					
i. David E. Erickson, in a field	survey on Se	plember 24, 19_ <u>97</u> ,		4	1 1	8	ģ	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					18	17	16	15	14	10
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					"	17	10	10	124	13
above were in conformance with the rul Court of Law; established, re-estal	les of the Michigan	 Board of Land Surveyors or b 	v a Decree of a	đ	19	20	21	22	23	24
expressed below:		www. To thousandinated, 100010	iou, ioung da	9	1 '				-	
NOTE: Not more than 4 corners	, all in the same	town and range, may be rec	orded	10 11	1	29	28	27	26	25
on this certificate.					31	32	33	- 34	35	36
A. Description of original mor	nument and acc	cessories and/or subsequ	ent restoration:	13	L					
Around 1825, R. Clark Jr D N87°W, 5" (3.30') and "W. Oal In 1886, H.F. Bean reported " S5°W, 81" (53.46') and "Y. Oa In 1973, R.E. Gutekunst - RLS capped fron on North side of 2, Page 293.	k 10, N63°W, 5' Both witnesse k 3, S82 1/2°W S #7863, record	" (3.30'). S Standing, found the (, 78 1/4" (51.64'). ded the corner as "Foul	old stake hole*	and rec	corded	two wi	tnesso V runn	es: "V	V. Oak	3, Set
6. Description of corner evide	ence found and/	for method applied in rest	oring or reestab	dishing c	orner:					
Found intact fireclay (FC) with Accepted found FC as a care monument in exact position of	eful and faithfu	Il perpetuation of the o	riginal corner.	found p Set a s	pieces d tandard	of brok d Jack	en bri son C	ck ben ounty	eath F concre	C. ete
C. Description of monument	for corner and a	accessories established to	perpetuate loca	ating the	position	of the	corner	:		
Set standard concrete monun	nent with alum	inum cap stamped "#29	9 245" .							
S 85° W Found nail and ta N 14° E Found 40" dead s		Oak	51.85'							
		side 8" Black Cherry	24.5' 5.33'		.4	~ ·	essencere F #810	THE .		
N 52° W Set nail and tag #	29245, Northe	ast side 6" White Oak	18.69'		SERVICE A	ATE O		11/6 V	<u>i</u>	
S 09° W Set nail and tag #		side 18" White Oak de 8" White Oak	16.3 2' 21.95'		\$ 5	DA	VID F			
NOTE: Bearings are magnetic	C				THE LOCK OF THE PARTY OF THE PA	ERI Land	CKSON Survey No. 9245 AND	URVE	THE STATE OF A SECOND	
$\langle a \rangle \langle a \rangle$	O						ri Firingh			

Surveyor's Michigan License No.

Signed by_