

Received: 02/14/2019 03:55 PM Recorded: 02/14/2019 04:04 PM State of Michigan - Kalkaska County Jo Ann DeGraaf, Register of Deeds

Book: 4 Page: 54

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's N	ame: _	Joshua R.	Davidso	on			Field	l Surve	y Date:	May 9,	2018			
For corner(s) in:		Kalkaska				County								
Original Pub	lic La	nd Survey	Corne	•		Corner Code								
S 30, 31		T	27N	R	5W	A11	_							
S	25, 36 T		27N R		6W	M11	4	A B (DE	E F (3 H	IJŀ	K L I	M ₁
S		Т		R										
S		Т		R			2	6	5	4	3	7	1 1 -	2
							3						1	3
Property Controlling Corner						Corner Code	4	7	8	9	-10	-11	12	4
s		T		_ R _			- 5						 	- 5
S		T		_ R _		-	- 6	18	17	16	15	14	13	6
S		Т		_ R _			- 7							7
S		ТТ		_ R _			- 8	19	20	21	22	23	24	8
Property Corner						Corner Code	9		20	21				9
S		Т		R			_ 10	- 30 -	29	28	27	26	25	10
s		Т		R			- 11							11
s		Т		R			1		00	00	0.4	35	20	Τ
S		T		R			12	31	32	33	-34	33	1 1	12
Protracted Public Land Survey Corner					Corner Code	⁻ 13 ¹	4 B (C D I	E F (з н	J	K L	_ M ¹³	
s		T		_ R		_	_							
S		T		R			_							
S		Т		R			_							
S		T		R			_							

Part A: Corner History

A11 – M11 – corner common to sections 30 & 31, T27N R5W, and sections 25 & 36, T27N, R6W

- See remonumentation LCRC L. 6, P. 657 for corner history.
- 2006 Remonumentation LCRC L. 6, P. 657 E. Farrier, PS #24594 Found 1 1/4" pipe set by M. Schaaf. Added remon cap.

N52°E 29.47' 4" Ironwood, set nail & washer

S47°E 26.20' 12" Basswood, set nail & washer S10°W 37.27' 16" Maple, set nail & washer S58°W 47.00' 20" twin Maple, set nail & washer

Kalkaska County peer group accepted the above monument as a careful and faithful perpetuation of the position of the original corner.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

A11 - M11 - corner common to sections 30 & 31, T27N R5W, and sections 25 & 36, T27N, R6W

Found Schaaf pipe, witnesses and remon accessories. Schaaf pipe (1½" X 4' long pipe in 8" X 8" X 8" concrete base) was leaning, probably hit by logging equipment. Replaced it with a stamped 4" DNR aluminum cap on 1" X 36" galvanized iron pipe. Placed stone on Northeast side of pipe. Reset Schaaf pipe & concrete as a guard post 1.65' North. Accepted monument as a careful and faithful perpetuation of the position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

A11 - M11 - corner common to sections 30 & 31, T27N R5W, and sections 25 & 36, T27N, R6W

a stamped 4" DNR aluminum cap on 1" X 36" galvanized iron pipe

N50°E 29.65' to set nail & tag at found nail in NW. side 6" Ironwood S49°E 26.13' to set nail & tag at found nail in NE. side 12 Basswood S11°W 36.95' to set nail & tag at found nail in W. side 20" Maple S62°W 47.55' to set nail & tag in SE. side 23" Maple North 1.65' to 11/4" pipe set as a guard post

February 12, 2019
Certifying Surveyor's Name

Date

Professional Surveyor's License No.: 46659

Prepared By: Joshua R. Davidson

Department of Natural Resources

8015 Mackinaw Trail Cadillac, MI 49601 OF MICH

JOSHUA R. DAVIDSON PROFESSIONAL SURVEYOR

POFESSION