KENT COUNTY REMONUMENTATION

LAND Filing

CORNER RECORDATION CERTIFICATE	REG.
Requirement of Act 74, Mich. P.A. 1970	R
!	

KENT COUNTY	Located In:	Corner Code #	AF OS
(County)	:	Tyrone Twp.	ν <u>α 19-29</u>
1. Public Land Surve	y T <u>10N</u> R <u>1</u> T R T R		80 °
Property Controllin in Section Miscellaneous Property in Sec.			11609 Register of Deeds Stamp & File Numbe
4. Lot No , F 5. Private Claims	Recorded Plat		A B C D E F G H I J K I
requirements of P.A. 74, N conformance with regulation United States Department of that the corner points men Board of Land Surveyors recovered, found as express	Aichigan P.A. of 1970, the corner in ns and rules therefore as required in of the Interior, Bureau of Land Man ationed in lines 3, 4 and 5 above we or by a Decree of a Court of a sed below:	Oct. 19 , 19 99 do hereby state that points mentioned in lines 1 and 2 above vin the current manual of survey instructions tagement or by a decree of a Court of Law are in conformance with the rules of the Millaw; established, re-established, monument and range, may be recorded	were in 5
H-8 1837 GLO 1896-1912 10' 10' 1934 Kent 6'' 1975 Surv 12'' 1983 LCR	Williams & Works " B. Oak SE 65' 20" W.P. st t Co. Wits Elm NE 31' 4" Poplar SSE rey J. Clapp ' Poplar SSE 51.30' C/L Elm C #3702 Hay	Found Steel Bar - set by J. Clapp	' 15" Maple SW 28.85' PP East 116.70'
H-8 Found Rerod	and Broken Cap inside an Iro	B. Elder N45°W 37.54′ Iron East of applied in restoring or reestablish on Pipe per the following remaining °W 28.84′ Iron Pipe East 33.03′	

Said Rerod inside Iron Pipe is 0.5' East and 0.5' South of Intersection of 1/4 lines and agrees ± with measurements of Clapp, Hay, Roosien and Nederveld.

The Rerod with Broken Cap inside an Iron Pipe is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set Stan	dard Kent County Monument in place of th	e Rerod w	ith Broken Cap and Iron Pipe
Nail &	tag NW side 20" Maple	S50°W	28.84'
Nail &	tag NE side P. Pole	N25°W	78.98'
1" Iron	Pipe	East	33.03'
Nail &	KC Remon. tag N. side 6" Poplar	S75°E	25.23'
Nail &	KC Remon. tag SW side 12" Poplar	S45°E	60.68'

KIRK **BREITELS** LAND SURVEYOR NO 3007

30077 Surveyor's Michigan License No.