	SUBVEY & REMONUMENTAT	ION O	- instruction			
1	NOV 2 5 1998	- ,		}		i,
U	SECTION LAND CORNER RECORDATION CERTIFICATE			LIB	**	
For corr	nore in Richland Twp.	Filing Requirement of Act 74, Mich. P.A. 1970			_ (,	ဏ္ဏ
- COLL		Located In:	Corner Code #	ļ •	OLERK	130 88
1. Pub	olic Land Survey	т <u>1S.</u> _R <u>10W</u>	. <u>B-7</u>	-	X-RESI	12 Pr

2page 330

Register of Deeds Stamp & File Number Property in Section , Recorded Plat_ Lot No. Private Claims IWM Job No. 30481 Allen H. McMachen , in a field survey on March 26 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned

2. Property Controlling in Section 3. Miscellaneous

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

NOTE: Not more than 4 comers, all in the same town and range, may be recorded

- Description of original monument and accessories and/or subsequent restoration:
- John Mullett, D.S., Set quarter Section post, Tam 15" S. 50° W. 14 lks., Tam 12" S. 82° E., 32 lks. (notes indicate 34.55 <u> 1827 -</u> chains between N.W. cor. & N1/4 cor.).
- F. Hodgman, C.S., "Found stake in march N. 82° W. from stump of one bearing & N. 50° E. 14 lks. from the stump of <u> 1887 -</u> the other. Set post 10½ lks. N.W. from North rail of railroad. Oak in South margin of bank S.W. 149½ lks.."
- <u> 1902 -</u> Ed Strong, C.Ŝ., "Tile buried by filling of railroad, set stone over. B. Oak 4" N. 02° W., 45 lks, rail about 6 feet East, (Strong's map indicates a 'surplus of 13 lks.' between N.W. cor. & N¼ cor. & divided equally into ¼ miles) Map also shows measure from N¼ cor. West to 1/8 cor. is 20.06½ chains, (1324.29′)."
 - B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron rod 2288.54 feet East of a surface marker at N.W. corner, Section 19. Dug under said iron to depth of 3.5' finding no additional evidence of corner. Property owner in area shared that in the early '70's the railroad nompany reworked the tracks between the two creek crossings with dozers and placed fill. Tile believed to have Deen removed during this excavation. All accessories to tile are now gone. It appears that the found iron was ⇒laced by an unknown surveyor at Strong's distance of 2288.88 feet (34.55 ch. [gov't] + 13 lks. [Strong's surplus]) From a surface marker at N.W. cor., N.W. corner was investigated and true historic marker (tile) was found to be 2.51 feet West and 0.06 feet South of surface marker. Placed 30" Harrison Monument at Ed Strong's 1902 measure of 2288.88 feet East from tile found at N.W. cor. and on line between N.W. cor. (tile) and the N.E. cor. (Harrison Monument). RATIFIED

BY KALAMAZOC COUNTY REMONUMENTATION.

Position of 30" Harrison Monument placed is accepted as a careful and faithful re-establish.

careful and faithful re-establishment of the position of the corner, Accessories:

60d Nail in West side of Triple 6" Elm N. 30° E. 4.50' Nail in 4" Maple S. 57° E. 27.89° 60d Nail in S.W. side of 8" Elm S. 35 ° W. 53.72' 60d Nail in South side of 6" Oak N. 85° E. 30.97' 1/2" iron rod N. 60° E. 2.51'

Signed by Surveyor's Michigan License No.

MICHI ALLEN H. McMACHEN PROFESSIONAL SURVEYOR No. 16935 PROFESSIONAL MANAGER DIO.

M APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL

REVISED JAN., 1983