

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mich P A 1970

Filing Requirement of Act 74, Mich. P.A. 1970	Call Remain Assemble
For corners in RICHLAND TOWNSHIP	SURVEY & REMONUMENTATION
Located In: Corner Code #	
1. Public Land Survey T 1S. R 10W. F-13 T R T R	FEB @ 8 2000 SECTION
2. Property Controlling S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L M 2 6 5 4 4 3 2 1
6. IWM, Job No. 32252	3 10 11 12
I, Allen H. McMachen, in a field survey on November, 19_99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4
NOTE: Not more than 2 corners, at in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate. RATIFIED BY KALAMAZOO COUNTY	11
REMONUMENTATION 47/	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restolation:	13
1825 - Mullett (V. 5, P. 166), Set qt. Sec. post, Oak 9" N: 76½° E. 57 lks., Oak 10" N: 1887 - Hodgman (V. 2, P. 211), Fd stk S. 84° E. 168 lks (110.9') from W. Oak stump of 1894 - Strong (V. 3, P. 65), Tile at S¼ of Sec. 33, the jog is 6 lks more than the ½ sum Strong measures jog at 106.59 feet to N¼ Sec. 4. He set on bisection. 1932 - W&W, Fd tile 1' below surface of road, 12" Hic N. 42° E. 53.55', 16" Hic S. 62 E. 36.98', 6" Hic S. 45° W. 44.5', 6" Oak S. 10° W. 23.45', Iron in line North 27.53' 1972 - Gove (L. 1, P. 243), Fd Iron rod, 12" Hic N. 60° E. 74.45', Fence North 34.03', 1981 - Ingersoll, Watson & McMachen, Inc., No surface marker found B. Description of corner evidence found and/or method applied in restoring or reestablishing corn	of the Sec corners jogs. 2° W. 50.0′, 4″ Oak S. 43° P.P. S. 60° W. 74.85′
No surface marker found. Found empty mon. box 8' South in center line travelway. Dug 4X4X4 at no evidence. Dug below empty mon. box, found no evidence.	106' West of bisection, found
RE-ESTABLISH SOUTH ½ CORNER: 1894 (V. 3, P. 65), Strong states that for N¼ of Sec. 4 Comst Section line, and that the jog (to tile at 5½ Section 33 Richland) is 6 links more than the ½ sum of the N. 3½° E. 34 lks (22.44), Oak 10″ S. 27¼° W. 47½ lks (31.3), Rec. jogs at NW 180 lks., at NE 131 = 35 meas of 161½ (106.59).	11/2 = 155.5, Strong shows
Ingersoll, Watson & McMachen, Inc. found tile at NW cor. and brick at NE cor., measured and bis Strong's Hickory tree witness still standing (now 23"). Held witness tree and bisected distance and intersection. Projected a line from found tile at SE cor. Sec 33 through set N¼ of Sec. 4, measured C. Description of monument for corner and accessories established to perpetuate locating the po	106.59 and reset 51/4 Sec. 33.
Position as established in Section "B" above is accepted as a careful and faithful reestablishment of the position of the original corner. Placed 30" Harrison Monument at said above position with monument box over, Accessories:	ALLEN H.
"PK" nail in East side of wood fence post North 29.58' "PK" nail in NW'ly side of 24" Hickory N. 75° E. 71.97' "PK" nail in NW'ly side of U. Pole S. 65° W. 77.43' Iron rod placed S. 65° E. 71.59' 5.8' North of centerline East & West road In line with fence extending North	McMACHEN PROFESSIONAL SURVEYOR NO. 16935
Signed by Washing Date	TOPESSION LZ/28/77
Surveyor's Michigan License No	