	`a'	SURV	ey 8 Cit	, N, Y - 3				_
		TEMONY	23	LAND COF			CERTIFICATI	
Fo	corners i	n AUG 2	7 1000		uirement	Of ACt 74, N	lich. P.A. 1970	and the second second
Kalamazoo Corner Code #								
Alamo Township								
1.	Public La	and Survey	T T	1 S R 12 — R — — R —		J-7		RALANAZOO RALANAZOO RATECORO RATECORO
2.	-	Controlling		R			_	
3	in Sectio Miscellar			R R			— 	contact of Danda Channe 9 File Number
0.	Property			R			- Ke	egister of Deeds Stamp & File Number
4	l ot No	, Re	icorded Dist					
5.		laims						— A B C D E F G H I J K L M
				į	.IBER	1 113	14	2 5 5 4 3 2 4 1
I, Robert E. Snell in a field survey on April 29 19 94								
A.		on of original m						
	1829:	United Sta Wh. Oak	tes Govei 6"		•		on Post. 35 Lks	
	·	Wh. Oak	15"	North South	37 14°	East West		
	1904:	: Ed Strong, County Surveyor; North 1/4 Post Section 23Dug thoroughly but found nothing. Set stone, large one, and 3 brick from 2 Bearing trees of 1878, which point agreed with doubled line from South.						
В.		Maple	14"	South	25°	West	43 Lks	
	Description 1963:	Butternut 14" North 06° West 49 Lks Set stake and brick East (Centerline of Road, 50 Lks) on of corner evidence found and/or method applied in restoring or reestablishing corner: Kalamazoo County Road Commission; Road plans show witnesses to North 1/4 Post. Stone removed during road construction and replaced by witnesses. 3/4" Steel Rod RATIFIED						
		Maple	22"	South	10°	East	40.881	BY KALAMAZOO COUNTY
		Maple	36"	South	65°	West	45.89'	REMONUMENTATION
	1070.	Telephone	Pole	North	60°	East	76.941	PEER GROUP Machen; Recorded LCRC 1-710 & 1-76
	1978:	Acro Engin	eering, l	robert Sau	ers, ing	jersoti Wa	LSUM & MCM	idenen; kecorded Luku 1-/10 & 1-/6

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

depth and found nothing else. Noted road had been reconstructed.

1979: Donald Pitts, Surveyor; LCRC 1-794, Same as Kalamazoo County (1963)

North 1/4 Post Section 23, T. 1 S., R. 12 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on September 15, 1994 and is accepted as a careful and faithful reestablishment of the position of the original corner. Found 3/4" x 24" iron rod. Removed iron rod and set 20" Harrison monument in its place with a monument box over.

Wilkins & Wheaton Engineering Co.; Found 3/4" Iron rod. Dug a hole 6' x 4' and to 7'

Guy Pole 36" Maple South 22° East 19.48' Exist. PK Nail in West Side CL Ravine Rd East 34' South 54° West 45.58' Exist. Double Head Nail in South 40° East 107.53' Exist. PK Nail in South Side Power Pole CL "D" Ave North 12' Monument Box North 64° East 46.01' Center of

9734

Surveyor's Michigan License No.

1994:

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983