

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corn	iers in Climax I w	p.			- 1		erio\	/EV &			
Kalama	3ZOO (County)	_ Located in:	Corner	Code #		REM	ONUN	/EY & //ENTAI	TOP	l	
1Publi	ic Land Survey	T <u>3S</u> R <u>9W</u> TR	- -	G-02		•	FEB (8 2000			
R					SECTION						
3. Misc	ection ellaneous erty in Sec.	S TR S TR S TR				Regis	ter of De	eds Stam	ρ& File	e Numb	er
 4 Lot N	No Recor	ded Plat			<u></u>						
4. Lot No, Recorded Plat 5. Private Claims						1 A B 2 - 6 -	C D E	F G 1	H I	J K	
Apr. 17 , 1996 & l. Robert E. Snell , in a field survey on Dec. 11 ,1998 do hereby state that unrequirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recover found as expressed below:					re in f the nd/or nigan	3 4 -7 5 6 -18 7 8 -19	3-17-20-20-	9	15	-11	-1: -1: -2:
NOTE:	Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					9			┼-		\dashv
r.	on and detailement.					10-30-	29-		27	-26	-2
						11 -	1	33	34	35	
A. Des	scription of origin	al monument and acces	ssories and/or su	ıbsequent restoratio	n:	12 31-		Ĭ L		ΪL	Ĭ
1826:	United States G	overnment Surveyors; s	et 1/4 Section po	ost.							
	Wh. Oa	ak 18" S. 5	54° E.29 1/2 lks.	Wh.	Oak 12"	S. 48	· W.	3 lks.			
1883:	F. Hodgman, County Surveyor; this corner was all dug out in the road. Ran the line from the Southwest corner to the Northwest corner of the Section and at a point in line between these corners and 40.00 chains Government Measure from the Southwest corner of the Section. Planted 3 ft. earthen post for corner and noted.										
	Y. Oak	12" S. 6	69 1/2° W . 96	3 1/4 lks.	Hick	ory 12"	S. 25	1/2° W.	125	lks.	
B. De	scription of corn	er evidence found and	l/or method app	lied in restoring or	reestabl	ishing co	ner:				5
1957:	W. Ingersoll, RLS #7227; set 3/4" iron by producing East and West 1/4 line to intersection of West line of Section over 1/8 corner. Measurement from West 1/4 post to center 1/4 post of Section 3 was 2,629.70'.										
1977:	Robert L. Sauer	s, RLS #10069; LCRC t	1, P-700 found	3/4" iron.							
		Power Pole		N. 70° E.	71.4						
		Power Pole 11 th Guard Rail Post We	est of East End	S. 60° E. Northeast	77.2 67.6						
1996:	Found 3/4" iron	30" below surface of roa	ad, using above v	vitnesses. Also four	nd 1/2" Iro	n and 3/4"	iron just	below sur	face.		
1999:		f Section to verify location from West 1/4 to Northwe			west corn	er Section	3 to We	st 1/4 post	meas	ured	
C. De	scription of mon	ument for corner and	accessories est	ablished to perpet	uate loca	ting the p	osition (of the cor	ner:		
G-02:	1999 and is account of surface. Iron se	Section 3, T. 3 S., R. 9 V epted as a careful and f t in 1957 survey by Will I 20" Harrison monumer	aithful reestablish iam Ingersoll, RL	nment of the position S #7227 by intersec	ı of the or	iginal com	er. Four	nd 3/4" iror	1 30" b	elow	
	PK Nail in South		Power Pole		55° E.		71.30				
	PK Nail in South PK Nail in North		Power Pale Guy Pole	S. 6	5° E. 60° W.		77.10 108.	70'			
		of Wood Post (Telephon			25° W.	a . 4	85.60)'			
Signed	by 0/84	w Z. Sn	<u> </u>	Date	e	1-16	-99			-	
Surveyo	or's Michigan Lice										