

## PORRESSION .

## LAND CORNER RECORDATION CERTIFICATE

LIBEROO3 PAGE 0236

	CONTRACTOR W	Filin	a Require	ement of Act 74, Mic	h. P.A. 1970	)		į	
For	corners in	•	J				50 N		-
	Lake	Located In	ı:	Corner Code ##			REGISTER		AKE
	(County)						S		033
1	Public Land Survey	T	R 11W	B-13			TER	ယ	COUNTY
١.	r ubite Land Ourvey	T						3-47-141-194	<b>Z</b> 3
			R					~~3	35
			R		_		N. Western		
2.	Property Controlling	S T	R		-		SG E	ದ್ದೆ	<b>=</b>
	in Section	s T	R		-			- <del> </del>	
3.	Miscellaneous	S T		-	- Re	egister of Dee	ds Stamp	& File N	lumber
	Property in Sec.	S T	R R		-		·	!	
	•							:	
		, Recorded Plat			<del></del>	- ABC	DEF	G H I	JKL
5.	Private Claims				<del>                                     </del>	- 2	- 5	3	
						3 1			<u> </u>
		J. Barrana and C. Carlon and C				ا ا ا			
	Robert L. Wetherell	, in a field survey on		August 12,	94	5			
do i	nereby certify that under	requirements of P.A. 74, M	lichiganP.A.	of 1970, the corner points:	mentioned	6			
in li	ines 1 and 2 above were	e in conformance with re-	gulations an	d rules therefore as requ	ired in the	7 18 1	~1/ <del>10-</del>		1
cur	rent manual of survey in	structions of the United S	tates Depart	tment of the Interior, Bure	au of Land	<u> </u>	<del>- - - -</del>		
Mar	nagement or by a decree	or a Court of Law and/or to with the rules of the Mich	iai ine come idan Board r	er points mentioned in lines of Land Surveyors or by a [	Decree of a	8 - 19	-2021-	22	<del>-23 24</del>
Cou	int of Law; established	i, re-established, monun	nented, re-r	nonumented, recovered,	found as	9	<del>- - - -</del>		
ехр	ressed below:					10 30	-2 <del>9   -</del> 28	27	<u>26</u> 25_
NO	TE: Not more than	4 corners, all in the sa	me town ar	nd range, may be reco	rded	11			
	on this certifica	te.				12 31-	_3233-	34	3536-
				d (		13			
A.	Description of origin	al monument and acce	ssories and	d/or subsequent restor	ation:				
	B-13 - South 1/4 Co	rner Section 31, T17N,	R11W, Lake	County, Michigan.				ı	
				- · · · · · · · · · · · · · · · · · · ·					
	1837 - John	Hodgson, G.L.O.	<u> 1972 - Cli</u>	nton E. Cole, LS 17615			rtificate		•
	#1 - 14" Pin	e N46 <sup>0</sup> W 28 Links		Surveyors) Broke Sect			Wetherel	i	-
	#2 - 14" Pin	e N18 <sup>0</sup> E 10 Links		ap indicates this corne			/2-s.E.1/		
				not indicated the metho	7 1		. & S.E.		
				given. Distances to W			of 2630.1	:	
			were 2455.	.29' & 2630.10' respect	rively.		nt identi	fication	or
						accessori	es given.	;	
В.	Description of corne	er evidence found and/	or method	applied in restoring or	reestablishir	ig corner:		:	
	- 47 - 1 4 <i>11</i> 0-	0 74 T179	04411 Loke	Coumty Michigan				!	
	B-13 - South 1/4 Co	rner Section 31, T17N,	KIIW, Lake	e country, Pricingan.				:	
	1 found a Ri	ass "T" iron % feet No	rth of the	centerline of East and	l West aravel	road and in	line with	old fen	ces to
	North and So	outh (down). The dista	nces to the	e Sections corner East	and West fil	well with th	ose repor	ted by La	akeState
	and that of	my 1981 survey. Neith	er of the (	5.L.O. accessories were	recovered.	No contrary	evidence	is presei	nt.
	4,1.1.	<b>,</b>				ì İ			
			ļ					ļ	
			!						
					1 1			ì	
								į	
		1	!					,	; :
						,		i !	1 1
					nto longtine	the position o	of the corr	ner:	
⊃.	Description of monu	iment for corner and ac	cessories	established to perpetu	ate locating	the position o	n tire con	101.	: 1
	D 47 . Amount 827	annon Continu Id. Tallu	0/14tt t =====	a County Michigan					
	B-15 - South 1/4 Co	orner Section 31, T17N,	KIIW, Lake	e country, michigan.					
	والمحاجمة والمحاجمة	the Blace NTH inon with	: .a 3///∜ ∪ '	24" re-bar with Lake Co	ounty Brass (	ap. and is a	cepted as	: a carefi	uland
		restablishment of the p			, 5, 655				
	iaitmut re	earanciament or the p	001 E (O) OI	wrighter corner.			يغو	TE OF	MA
	P. Pole Nort	th 54.08' (60d spike in	W. side)					B.T. C.	- Holy
		47 <sup>0</sup> E 44.93' (60d spike		de of tree)				BANK	
		35°W 37.0' (center of t			: 1		- \$ <b>/</b>	WETHE	RELL

PATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH R.A. 345 CHAIRMAN C. Y. W.

24" Maple N80°E 101.93' (60d spike in S. side of tree)

LS 24626

Signed by

Burveyor's Michigan License No.

, 1994

OVED BY MICHIGAN STATE BOARD OF CAND SURVEYORS ARE. 28, 1979

REVISED MAY 14, 1975

REVISED JAN., 1983

October