NOV 1 5 1994

## LAND CORNER RECORDATION CERTIFICATE

LIBEROO3 PAGEO244

-	corners in COMMISSION	Filing Requ	irement of Act 74, Mic	h. P.A. 1970		
ю		cated in:	Corner Code ##			<u> </u>
	(County)	outes in.	Oomer Code 44			m
1.	Public Land Survey T	7 17N R 11W	E-13	-	T 27 3 REGISTER	LAKE COUNTY
		R		-	23 PH 10 OF DEED	السيا
		Г R`		-	DE DE	
2	Property Controlling S T	Г R Г R		-	DEED DEED	
	in Section S T	Г R <u></u>		-	DS E	
3.	Miscellaneous S T	Г R <u>.</u>	.	Regi	ster of Deeds Stamp & File N	umhar
	Property in Sec. S T	Г <u></u> R		legi	ster or beeds stamp a rife in	umper
4.	Lot No, Recorded Plat	t	<u> </u>		ABCDEFGHI	JK
5.	Private Claims	<u> </u>			2 6 5 4 3	$\top$
	•	:	,		3	
		1	1	.		<del></del>
	Robert L. Wetherell , in a field su		August 3,	94	4 7 8 9 10	-11-
ا, ــ ام	nereby certify that under requirements of P			mentioned	5	
	nes 1 and 2 above were in conformance				6 18 17 16 15	-1'4
	rent manual of survey instructions of the				7	
	nagement or by a decree of a Court of Law		1	2 1 3 1	8 19 20 21 22	-2 <sup>3</sup>
	we were in conformance with the rules of t art of Law; established, re-established,				9	
	ressed below:				10 30 29 28 27	_26
NO	TE: Not more than 4 corners, all in	the same town	and range, may be recor	rded	11	
	on this certificate.				12 31 32 33 34	_35
-			• 1		13	
Α.	Description of original monument ar	nd accessories a	and/or subsequent restore	ation:	•	
	E-13 - Section corner common to Sec	ctions 32 and 33	. T17N. R11W. Lake Co	Mi on the Cou	inty Line.	
	1837 - John Hodgson, G.L.O.		1929 - E.E. Sours, Engi	1 1 1	1979 - R.L. Wetherell, LS 2	24624
	#1 - 8" Beech N42 <sup>O</sup> W 34 Links #2 - 10" Beech N67 <sup>O</sup> E 20 Links		Developed Plat of "Star	1 4	Found Plow Point. Raised w	vith
			Set monument 33' North	of	1/2" Capped Iron.	
			Section corner.		#4 - 8" W. Pine N44 <sup>0</sup> E 49.30	
	Undated - George Johnson, La	ake Co. Surveyor			#5 - 9" Beech N30 <sup>0</sup> W 4	
	Plow Point				#6 - 18" R. Pine \$34 <sup>0</sup> E 68.7	791
	#3 - 10" Y. Pine S.E. 87.5"					
			\$			
₿.	Description of corner evidence foun	id and/or metho	d applied in restoring or r	reestablishing o	corner:	
	E-13 - Section corner common to Sec	ctions 32 and 37	T17N R11U lake Co N	Mi on the Cou	inty Line	
	2 10 Scot (S) Columbia Columbia	2010110 22 414 20	, , , , , , , , , , , , , , , , , , , ,		<u>,</u>	
	I found 1/2" Capped Iron and	d Plaw Point. J	also found a 1" pipe 33	feet North of	corner, being the Southeast o	corner
					3 above. Corner is in the ce	
	a East and West gravel road	and in line wit	h fence to the North. Co	ondition of the	accessories are as follows:	#1
	Gone, #2 Gone, #3 Found in g	good condition,	#4 Found in good condition	on, #5 Found in	good condition, #6 Found in	good
	condition.		·			
			,			
					•	
11				.		
•	Description of monument for corner	and access	a aatablichad ta narratus	ata locating the	nosition of the corner	
C.	Description of monument for corner	and accessome	a carabilation to betherno	are recalling the	position of the comer.	

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP
IN ACCORDANCE WITH PA: 345
CHAIRMAN

I replaced the 1/2" Capped Iron with a 3/4" x 24" reb-bar with Lake County Brass Cap, and is accepted as a careful and

faithful re-establishment of the position of the original corner.

10" Beech N33<sup>O</sup>W 40.18' (60d spike in S.W. side of tree) (#5) 11" W. Pine N46<sup>O</sup>E 49.34' (60d spike in N.W. side of tree) #4)

18" R. Pine  $560^{\circ}E$  87.94' (60d spike in N. side of tree) (#3) 18" R. Pine S38<sup>0</sup>E 68.80' (60d spike in N.E. side of tree) (#6)

Surveyor's Michigan License No.

Signed by .

Terferen betignaan valerbelen aan de daar val eer beske beskelen tekstelen beskelen de daar op daar op de ste

E OF MICHIGA

ROBERT L. WETHERELL

LAND SURVEYOR NO. 24824