NOV 1 5 1994

	EARD CORNER RECORDATION CERTIFICATE	MirTI
The second secon	Filing Requirement of Act 74, Mich. P.A. 1970	i voc 🔿 💳
or corners in COMMISSION		

	(County)	Located In:	Corner Code ##		Oct 21  REGI
1.	Public Land Survey	T R			T 27 3 23 PM
		T R T R T R			OF DE
	Property Controlling in Section	S T R S T R			PH 'SH
3.	Miscellaneous Property in Sec.	S T R S T R			Register of Deeds Stamp & File Number
4.	Lot No, F	Recorded Plat			: A B C D E F G H I J K
Э.	Private Claims		· · · · · · · · · · · · · · · · · · ·		2 6 5 4 3 2
ŀ.	Robert L. Wetherell	, in a field survey on	August 8, 94		4 7 8 9 10 11
in I cur Ma abo Co	lines 1 and 2 above were in trent manual of survey instr nagement or by a decree of the were in conformance wi	n conformance with regulatio ructions of the United States E a Court of Law and/or that the ith the rules of the Michigan Bo	in P.A. of 1970, the corner points mentions and rules therefore as required in Department of the Interior, Bureau of corner points mentioned in lines 3, 4 a part of Land Surveyors or by a Decreed, re-monumented, recovered, foun	n the Land and 5 e of a	8 19 20 21 22 23
NO	OTE: Not more than 4 con this certificate.		wn and range, may be recorded		11
A.			s and/or subsequent restoration	:	13
	<u> 1837 - John Hod</u> #1 - 14" Hemloc	ection 34, T17N, R11W, Lake Igson, G.L.O. :k N26 <sup>0</sup> E 31 Links :k N31 <sup>0</sup> W 34 Links	1978 - R.L. Wetherell, LS 24 Steel Fence Post #5 - 48" Maple N58 <sup>O</sup> E 38.61' #6 - P. Pole S32 <sup>O</sup> E 103.80' (#	(#3)	1990 - Gerald Gray, L.S. 17741 Steel Bar #8 - 48" Maple AZ 58 <sup>0</sup> 38.9' #9 - Cor. Fe. Post AZ 315 <sup>0</sup> 42.6'
	<u>Undated Newaygo</u> Steel Post #3 30" Maple N5 #4 P.Pole S40 <sup>0</sup> E		#7 - 6" Box Elder S31 <sup>0</sup> v 44.02 P.A. 132 - Series "J", No. 19 Newaygo County Records	5,	#10 - P. Pole AZ 148 <sup>0</sup> 103.8 <sup>1</sup> L.C.R.C Liber 03, Page 106
В.			hod applied in restoring or reesta	ablish	ing corner:
	H-13 - <u>S.1/4 Corner Se</u>	ction 34, T17N, R11W, Lake	. Co., Mi.		
	point up. Under pipe and steel in hole. The Gravel Road to condition, #5	er plow shoe I found axe h sign post and replaced wi corner is 3.5 feet North o South. Condition of acce	ewned pointed cedar stake (5" in th Lake County Brass Cap Monumer of centerline of East and West Gr ssories are: #1 Gone, #2 Gone, # 6 Found in good condition, #7 Go	n diam nt, le navel 43 Fou	the sign post I found a plow shoe with eter) in sand. I removed the 1-1/4" aving old cedar stake and plow shoe Road and 12 feet West of centerline of and in good condition, #4 Found in good 8 Found in good condition, #9 Found in
٥.	Description of monume	nt for corner and accessor	ries established to perpetuate loc	cating	the position of the corner:
			†	T.	

H-13 - S.1/4 Corner Section 34, T17N, R11W, Lake Co., Mi.

I set a 3/4" x 24" rebar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. TE OF MICHIG

 $50^{\rm H}$  Maple N58  $^{\!0}\text{E}$  38.65  $^{\!1}$  (60d spike in S.E. side of tree) (#5) P. Pole \$36°E 103.87' (60d spike in N.E. side of pole) (#6) P. Pole N67°W 134.09' (60d spike in South side of pole)

S.W. corner of Pole Barn N6<sup>0</sup>E 133.7

Signed by

Date

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345 CHAIRMAN CA. Z.W.. DATE 10 - 25-94

IVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

ROBERT L

WETHERELL LAND SURVEYOR

MO. 24624

Surveyor's Michigan License No.