

JAN 2 5 2001

## LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For Lal	r comers in ke		Loc	ated in:		Corner Cod	!e#		LAK	E C(		ГҮ, 🕽	11. 02	48	
1.	Public Land Survey		T 17 N			R 14W C-3		H		7 5 10 26 AM '00					
						<u>R</u>		Allery Myers REGISTER OF DEEDS							
				T		R		R	EGIS	∂ TER	יאב שיי	Dien	ري		
				T		R	********	,,		J ( C.1)	. 01	VEED	'5		
2.	Property Controlling S		<u>T</u>		_R 										
	III Goddon	<u>s</u>	<u>T</u>		R			Registe	r of D	Deeds	Stam	1p & F	ile N	umbe	
3.	Miscellaneous Property in Sec.	<u>s</u>	<u>T</u>		_R							<u>-</u>			
	Lot NoReco	S rded Pla	T at		R			1 l	В	СВІ	EFG	H ]	JK	LM	
		a field au	115 (0)	on Ma	rob 1		2000 do	2	6	5	4	3	2	1	
I, Robert L. Wetherell, in a field survey on March 10, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner										8	9	10	11	12	
points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United									18	17	16	15	14	13	
States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were									19	20	21	22	23	24	
In conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Of a Court of Law, established, re-established, monumented, re-monumented,									30	29	28	27	26	25	
	covered, found as expre			long E 6	7 9.	. Q TITN D	1 <i>4</i> W	11 12 13	31	32	33	34	35	36	
<u>U-</u>	3 - Section corner con	inion to	oecti	ions 5, 0	, / 🛇	0, 11/N, K	<del>1771</del>	101							

A. Description of original monument and accessories and/or subsequent restoration:

1838 - J. Hodgson, G.L.O.

#1 - 4" Beech N24°E 32 Links

#2 - 6" Beech S25°W 13 Links

1908 - J.W. Nichoson, Co. Sur.

#3 - 36" W. Pine Stump N44°E 71 Links

#4 - Measured 2649.24' East to 1/4 post.

1914 - G. H. Johnson, Co. Sur.

Angle Iron

#3 - School House N72°W 230 Links (151.8')

1951 - G. Blass, LS 5489

½" Iron Pin

#6 - Fence Post N48°W 44.58'

#7 - U.S.G.S. Bench Mark S45°W 53.62'

#8 - P. Pole S42°E 45.82'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found a 1/2" Iron Pin which was in the centerline of roads North and South and 2 feet more or less North of road East and West.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Measured 2660.90', #5 Found in good condition, #6 gone, #7 Found broken, #8 New Pole.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1/2" Pin with a 3/4" x 24" rebar with Lake County Remon Cap, and is accepted as a careful and faithful reestablishment of the position of the original corner.

S.E. Corner School Foundation N68°W 151.88' (#5)

4" B. Spruce N44°W 125.69' (center)

P. Pole S38°E 50.06' (Nail N.E. side)

30" W. Pine N49°E 155.59' (60d spike W. side)

P. Pole N16°E 166.91' (P.K. nail W. side)

PATREEN Y TELLUT IN ACCORDANCE METERA. 345 CHARGEN R. X.W. DATE H. II-2000



7. Wetherell Signed by Surveyor's Michigan License No. 24624

Date April 12, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING JANUARY, 1999