REMONUMENTATION

NOV 1 5 1993

LAKE COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Eiling Requirement of Act 74 Mich DA 1070

LIBERDO3 PADED 180

EΛ	or corners in LAKE	ring nequi	Tentent Of Act 74, Mich	i, r.m. 1971	,							
_		Located In:	Corner Code ##			•	REC	Q		•	LAK	
1.	Public Land Survey	T 17N R 14W	D-13				(S) 1 1	2000	င္သာ		83	Ž
		T R T R T R					0 30 N	7.1	5		UNITY,	77
2.	Property Controlling in Section	S T R S T R	,	- ')EEDS	Ochan	EF.	·	*****	
3.	Miscellaneous	S T R S T R		Re	gister	of De		amp		Numt	er .	
	Property in Sec.		ATT A STATE OF THE	<u> </u>								
4.	Lot No.	Recorded Plat	· · · · · · · · · · · · · · · · · · ·		<u>A</u> _	вс	D E	F	G H	ıj	K L	. M
5.	Private Claims				_ 2	6-	- 5	-4-	3-	2-		\prod_{-}
					3	1	11	1			-	ot
					4 <u>-</u>		- 8		<u> </u>		+	12-
r, Robert L. Wetherell in a field survey on October 26, 1993 . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						+-+	+	-			+-	\vdash
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land							-17	1 ⁶	15	14-		13
	rrent manual of survey ins inagement or by a decree (8			1			1	<u> </u>			
	above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as							_21	22	23-		
	pressed below:	re-established, monumented, re-	-monumentea, recoverea, r	ound as	10	30	-29	 28	27	26		25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						31	-32	_33	34-	35-		36
A,	Description of origina	al monument and accessories ar	nd/or subsequent restorat	ion:	13 📖						!	
	9.47 (4.11 6	Saladas 70 as aba aliman läna.	747H 04/H)									

(1/4 Corner Section 32, on the county line, T17N, R14W)

GLO Re-survey 1856 by Thomas Whelpley #1 | 12" W. Pine N 34 1/2°W 11 Links #2 14" W. Pine S 38 1/2°W 16 Links

1968 by R.A. Griffin, LS 13584 W. Oak N32^OE 73.36¹ W. Oak \$33°E 63.91' #5 5" W. Oak \$49°W 72.81' #6 6" W. Oak N24⁰W 68.18' 4" Sq. x 7' Pine Post

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - D-13 (1/4 Corner Section 32, on the county line, T17N, R14W)
 - R. A. Griffin in 1968 could not find evidence of either the corner monument or of bearing trees. Griffin reestablished the location of corner by single proportional measurement (2636.79' & 2636.70') on a straight line between the S.E. corner and the S.W. corner of Section 32, T17N, R14W. Griffin placed a 5" Sq. x 36" Concrete Monument with brass cap for the corner, (recorded in Liber 01, Page 19). Found Griffin's Concrete Monument in good condition. Condition of recorded witnesses is: #1 Gone; #2 Gone; #3 Found in good condition; #4 Found in good condition; #5 Found in good condition; #6 Found in good condition; #7 Found in good condition.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - D-13 (1/4 Corner Section 32, on the county line, T17N, R14W)

Accepted R. A. Griffin's Concrete Monument with brass cap as a substantial marker for the 1/4 corner, and is accepted as a careful and faithful reestablishment of the position of the original corner.

Date

 $N32^{\circ}E$ 73.36' (10" dock spike in N.W. side of tree) (#3) W. Oak 63.91' (10" dock spike in N.E. side of tree) (#4) W. Oak

72.81 (10" dock spike in S.E. side of tree) (#5) s49⁰W ⊎ Oak

N24⁰W 68.18' (60d. nail in S.W. side of tree) (#6) 9" W. Oak

4" Sq. x 7' Pine Post 32.97' North (#7)

LS 24624

Surveyor's Michigan License No.

SURVEYOR

ROBERT L

WETHEREL

LAND

ED LAND FORM APPROVED BY MICHIGAN STATE BOARD OF CASE SO VEYORS, JAN. 28, 1971

Approved by Peer Review Group OCT- 27 1993 Robert L. Wetherell, County Representative

REVISED MAY 14, 1975