## LAND CORNER RECORDATION CERTIFICATE

Fr	or corners in page 0.5 1505	Filing Requirement of Act 74, Mich. P.A. 19	1BERUU3 MAULU269
· · ·	Lake (County) CONNINGSION Locate	ed In: Corner Code ##	·
	Public Land Survey T	R	STATE OF MICHIGAN RECORDED 4 DAY OF COUNTY OF LAKE 19 9 FAD. 81 O'Clock 11:30 PM.  REGISTER OF DEEDS  REGISTER OF DEEDS  REGISTER OF DEEDS
4.	Lot No, Recorded Plat		A B C D E F G H I J K L M
5.	Private Claims		2 0 5 4 3 2 1 1
in Cu Ma ab Co	hereby certify that under requirements of P.A. I lines 1 and 2 above were in conformance wit rrent manual of survey instructions of the Unit inagement or by a decree of a Court of Law and, ove were in conformance with the rules of the t	y on, 19, 19, 74, Michigan P.A. of 1970, the corner points mentioned the regulations and rules therefore as required in the ted States Department of the Interior, Bureau of Land /or that the corner points mentioned in lines 3, 4 and 5 Michigan Board of Land Surveyors or by a Decree of a onumented, re-monumented, recovered, found as	3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 10 10 10 10 10 10 10 10 10
NC	OTE: Not more than 4 corners, all in the on this certificate.	e same town and range, may be recorded	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
۸			12 31 32 33 34 35 36
Λ.	A. Description of original monument and accessories and/or subsequent restoration:  G-2 - 1/4 corner common to Sections 3 and 4, T18N, R12W, Cherry Valley Township, Lake Co., Mi.		
	1838 - John Hodgson, G.L.O. #1 -10" Spruce S64 <sup>0</sup> E 28 Links #2 - 6" Cedar N47 <sup>0</sup> W 28 Links	1977 - Carl Roser, L.S. 12028 (D.N.R. Sur.) Restored corner by standard BLM instruction area of North and South fence on ground #3 - 11" Cedar Stump North 20.3' #4 - 5" Cedar N85°E 8.7' #5 - 6" Cedar S35°E 6.8' L.C.R.C. Liber 02, Page 352.	in Survey recorded in Liber 3, Pg. 269. Found D.N.R. monument 2714.17 feet South of N.W. corner of Sec. 3.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			•
G-2 - 1/4 corner common to Sections 3 and 4, T18N, R12N, Cherry Valley Township, Lake Co., Mi.  I found D.N.R. aluminum capped pipe monument in large Cedar swamp, 300 feet more or less North of two track ro Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Found remains, #4 Found down, #5 Found in g condition.			re or less North of two track road.
	IN ACCORDANC CHAI	CO. PEER REVIEW GROUP CE WITH P.A. 3459 RIMAN C. T. U. ATE 11/8/94	••
c.	Description of monument for corner and	d accessories established to perpetuate locating	g the position of the corner:
	G-2 - 1/4 corner common to Sections 3	and 4, T18N, R12W, Cherry Valley Township, Lake	e Co., Mi.
	the position of the original cor 9" Cedar S10 <sup>O</sup> E 70.15' (60d spike 7" Cedar S54 <sup>O</sup> W 41.48' (60d spike 7" Cedar N20 <sup>O</sup> W 40.34' (60d spike	in W. side of tree)	ROBERT L. WETHERELL LAND SURVEYOR NO.
- 0	ned by Sabert 7. Wet	tuell Date 1/1	9 94 24624 CE E
Surveyor's Michigan License No FORM APPROVED BY MICHIGAN STATE BOARD OF LINE SUBJECTION 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983			

TO TOTAL PARTITUTE OF THE SERVER STANDARD OF A CONTROL OF THE OWNERS AND THE SERVER STANDARD OF THE CONTROL OF THE OWNERS AND THE OWNERS AND