

JAN 2 5 2001

## LAND CORNER RECORDATION CERTIFICATE

SECTION

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

For corners in Lake			Located in:			Corner Code#				· 1	RECO	RDE	ED			
1.	Public Land Survey		T_18 N		R 12 W	INFR	) ( )	.AKI	E CO	UNT	Y. M	1.				
			<u>T</u>			R			DEC 8 11 17 AH '00							
				т		R		1								
				Τ		R			4	٤	C. s.		e e a a	ا ا		
3.	Property Controlling	S	Т		R				R	EGISTER OF DEEDS						
	in Section  Miscellaneous  Property in Sec.	s	т		— R			——————————————————————————————————————								
		s	т		R			Regi	ste	r of [	Deeds	Stan	1p & F	ile N	ımber	
					_											
	Lot NoRecor								A	В	C D 1	e F C	3 H I	IJ	CL M	
5.	Private Claims								2	6	5	4	3	2	1	
1, Robert L. Wetherell, in a field survey on March 16, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United  3 7 8 9 10 11 12 6 18 17 16 15 14 13												10	11	12		
												13				
States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were										19	20	21	22 (	23	24	
In conformance with the rules of the Michigan Board of Land Survey Of a Court of Law; established, re-established, monumented, re-mo							veyors or by a Decre	e	9	30	29	28	27	26	25	
recovered, found as expressed below:					.0,10	inomou, ro	1	11 12	31	32	33	34	35	36		
I-8 - 1/4 Corner common to Sections 22 & 23, T18N, R12W																
A. Description of original monument and accessories and/or subsequent restoration:																
	1838 - J. Hodgson, G.L.O. #1 - 8" Pine S19°E 10 Links #2 - 9" Pine N19°W 10 Links					1916 - G.	<u>r.</u>	1978 - C. Roser, LS 12028 L.C.R.C Liber 02, Pg. 350								
							agon Tongue Oak N77°W 62-1/2'	-	Found 3/8" x 1-1/4" Iron							
	#4 - 5" J. Pine S48°30'W 85								Raised with 1/2" x 15" Pipe							
											ak N45°W 50.3'					
										#6 - 9" B. Oak \$55°W 47.2' #7 - Cedar Post - West 33'						
В,																
I found a ½" x 15" pipe directly over the ¼" x 1-1/4" Wagon Tongue. Corner is in the centerline of North													and S	South	road.	
	Condition of the acce good condition, #7 Fo			follows:	#1	Gone, #2 G	one, #3 Gone, #4 Go	one, #5	Foi	ınd i	n goo	d con	dition	, #6 I	ound i	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the ½" pipe with a ¾" x 24" re-bar with Lake County Remon Cap, and is accepted as a careful and faithful CF WILLIAM reestablishment of the position of the original corner.

7" W. Oak N42°W 50.57' (60d spike in N.E. side) #5

9" W. Oak S42°W 57.58' (60d spike in N.W. side)

3" W. Pine S29°E 81.94' (60d spike in N.E. side)

4" W. Pine N42°E 78.37' (60d spike in E. side)

HATIFIED BY THE LAKE CO. PIER REVIEW GROUP 5 IN ACCORDING WITH P.A. 345 CHAMMAN RYW DATE 12-5-260

Date December 6, 2000

Bout & Ultherell Surveyor's Michigan License No. 24624

ROBERT

ETHEREL

RVEYOF

LAND