REMONUMER

RECORDED LAKE COUNTY, MI.

NOV 2 1 1997

LAND CORNER RECORDATION CERTIFICATE

LIBER O O 4 PAGE O O 2 4
TE SEP 12 10 30 AM '97

Fo	r corners@OMMicasica	Riling F	Requirement of Act	74, Mich. P.A. 197							
	Lake	. Located in:	Corner C	ode -//	Chiman in M. Kindard						
	(County)			50e -77	REGISTER OF DEEDS						
1.	Public Land Survey	19N 13 T R _ T R _ T R _									
	in Section Miscellaneous	T R _ S T R _ S T R _ S T R _ S T R _			legister of Deeds Stamp & File Number						
4.	Lot No, Rec	orded Plat									
5.	Private Claims				A B C D E F G H I J K L						
	Robert L. Wetherell		April 3,	97	3						
I, _	, it	n a field survey on	дрі (t. Э,	19	5 10 11 12						
abo Cor exp	nagement or by a decree of a Cove were in conformance with the part of Law; established, re-expressed below: TE: Not more than 4 corn on this certificate. Description of original more	ne rules of the Michigan I stablished, monumente ers, all in the same to	Board of Land Surveyors d. re-monumented, re- own and range, may	s or by a Decree of a covered, found as be recorded	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36						
	G-5 - Section corner commo				Co Mi						
	1838 - S. Sibley, G.		9 - Harden - U.S.F.S.	966 - Robert L. Griffin, LS 13584							
	#1 - 12" Pine N78 ⁰ E #2 - 14" Pine S72 ⁰ W	37 Links Iron 7 Links #3	n Bolt - 16" R. Oak N59 ⁰ E 73 - 9" R. Oak S14 ⁰ E 53	.75' For .5' 5"	C.R.C Liber O1, Page 156 und Iron Bolt - Replaced with Concrete Monument						
	Undated County Surve	eyors Book			- 9" B. Oak N56°E 95.24'						
	2' Long Bolt #3 - 12" B. Oak N57 ⁰	PE 73.0'	#6 - 5" W. Oak S50 ⁰ 96.60' #7 - 5" W. Oak S51 ⁰ W 144.89' #8 - 5" Maple N17 ⁰ W 131.29'								
3.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:										
	G-5 - Section corner common to Sections 9, 10, 15 & 16, T19N, R13N, Peacock Twp., Lake Co., Mi.										
	I found a 10" dock sedge of road to Sout	•	5" x 36" Concrete Mo	nument in the center	r of East and West road and on the East						
		ories are as follows: Found in good condit			Found in good condition, #6 Found in						

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 - Section corner common to Sections 9, 10, 15 & 16, T19N, R13W, Peacock Twp., Lake Co., Mi.

I	accepted the	5" x	30"	Concrete	Monument	as a	substantial	marker,	and	is	accepted	as a	careful	and	faithful
۲ŧ	e-establishmen	t of	the	position	of the o	rigir	al corner.						ت.	A PORT	TE OF MI

10" W. Oak \$48°E 96.55' (dock spike in S.W. side) #6

10" W. Oak \$57⁰W 144.87' (dock spike in S.E. side) #7

15" B. Oak N58°E 95.26' (dock spike in N.W. side) #5

■veyor's Michigan License No.

WETHERELL SURVEYOR NO. 24624

ROBERT L

15" B. Oak N58°E 95.26' (dock spike in N.W. Side)

8" W. Oak N45°W 109.27' (60d spike in N.E. side)

RATIFIED BY THE LAKE CO. PEER REVIEW GROWN ACCORDANCE WITH PA. 345

CHAIRMAN A.Z.C...

DATE 8-21-97