SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970


LIBER OO4		74
REO X	Oct 29	LAKI
REGISTER OF DEEDS		RECORDED
M. Wholes	40 PH	NTY.
دهسا EDS:	عد پۇر	7

For corners in Lake	Located in:	Corner Code #	
(County)	19N	144	H-1
1. Public Land Survey	TR TR TR		
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR		

Register of Deeds Stamp & File Number

4. Lot No, Recorded 5. Private Claims	Plat		
Robert L. Wetherell	Oct. 8	98	
in requirements of P.A. 74, Michigan P. conformance with regulations and rules United States Department of the Interior that the corner points mentioned in in Board of Land Surveyors or by a Drecovered, found as expressed below:	or, Bureau of Land Management nes 3, 4 and 5 above were in con Decree of a Court of Law; esti	or by a dec	ree of a Court of Law and for with the rules of the Michigan

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

H-1 - North 1/4 corner Section 3, T19N, R14W, Lake Co., Mi.

1908 - J.W. Nichoson, Co. Sur.

1-1/2" Iron Pipe

#1 - Pine Stump N1-1/20E 50 Links

#2 - Pine Stump S48⁰E 62 Links

1959 - G. Blass, LS 5489

"Found 1-1/4" x 26" Pipe - raised with 1/2" x 12" pipe with 3 beer

bottles around". Corner is equal distance between N.W. cor. & N.E. cor.

of Sec. 3, and on Line between 5.1/4 & S.E. cor. Sec. 34, T20N, R14W.

#3 - Tw. Maple N22°E 52.18'

#4 - Railroad rail (Fence Post) S3^OE 34.14'

#5 - 10" W. Oak S21°W 64.00'

HATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345 CHAIRMAN E. X. W. BATE 10-27-98

#6 - 7" W. Oak N44°W 73.40" B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

H-1 - North 1/4 corner Section 3, T19N, R14W, Lake Co., Mi.

I found a 1/2" pipe inside a 1-1/4" pipe with beer bottles around it. Corner is in the center of East and West blacktop road.

Condition of the accessories are as follows: #1 Found remains #2 Gone, #3 Gone, #4 Found in good condition, #5 Found in good condition, # 6 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-1 - North 1/4 corner Section 3, T19N, R14W, Lake Co., Mi.

I replaced the pipe with a 3/4" x 24" rebar with Lake County Brass Cap, this position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

Marrow gauge railroad rail S8°W 34.40" - #4

30" B. Oak N34°W 60.05' (60d spike in 5.W. side)

14" W. Oak S49^OW 49.89' (60d spike in S.E. side)

16" W. Oak \$30°W 64.38' (60d spike in E. side) #5 3/4" x 24" rerod with Brass Cap (S.1/4 Cor. Sec. 34, T20N, R14W) - West - 623.57'

Signed by Robert T. Wetherell 24624 Surveyor's Michigan License No._

Date 10-29-98

of wienies ROBERT WETHERELL LAND SURVEYOR NO. 24624 The same

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995