MAY 1 8 1998

SECTION

Surveyor's Michigan License No. 24624

LIBER 004 PAGE 0122

LAND CORNER RECORDATION CERTIFICATE

For corners in		ng Requirement of A	ct 74, Mich. P.A. 1	1970			
(County)	Located In:	Corner Code #			R ()	APR	<u>-</u>
1. Public Land Survey	T_20N R TR TR	14W c-13			CISTER	三 三 3	RECORDED LAKE COUNTY,
2. Property Controlling in Section3. Miscellaneous Property in Sec.	TR S TR S TR S TR S TR			Register o	REGISTER OF DEEDS Deeds	94 98 Fil	.
4. Lot No, Recor	rded Plat					· · · · · · · · · · · · · · · · · · ·	
5. Private Claims	ided Flat			ABCD	EFG	ні	JKL
				2 - 6 - 5	5	_ 3	- 2 - 1
Robert L. Wetherell	, in a field survey on	Jan. 17 98	harahu atata at a	3		-	
requirements of P.A. 74, Michiga conformance with regulations and United States Department of the I that the corner points mentioned Board of Land Surveyors or by recovered, found as expressed be	an P.A. of 1970, the come I rules therefore as require Interior, Bureau of Land M I in lines 3, 4 and 5 above I a Decree of a Court o	er points mentioned in lines ed in the current manual of si fanagement or by a decree of were in conformance with the	urvey instructions of the of a Court of Law and /or	5 -19 -1	7 16	15	-14 13
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			orded	9			1 24
on this certificate.				10 30 2	928	_27	-2625
				11			
				12 31 32	2-33-1	34	35 36
A. Description of original mo		·					
C-13 - Section corner c	ommon to Sections 31	& 32, T20N, R14W, ELI	k Twp., Lake Co., M	ti.			
<u>1837 - Mullett,</u> #1 - 10" Sugar N #2 - 18" Hemlock	156 ⁰ E 56 Links	1908 - J.W. Nichoson "Found Old Stakes" #3 - 7" Hemlock N6 ^O t #4 - 6" Beech N38 ^O E	W 47-1/2 Links	1965 - Robert Found a badly West of corner T19N, R14W. No accessories	rotted squ common to	are stak	& 6. of
B. Description of corner evid	lence found and/or me	ethod applied in restoring	or reestablishing co.	rner:			
C-13 - Section corner c	ommon to Sections 31	& 32, T20N, R14W, EU	k Twp., Lake Co., M	l <u>i.</u>			
(L.C.R.C Libe	r 01, P g. 173). I p	in calls for as an accoresume Griffin replace 5 & 6 of T19N, R14W is	ed the rotted wood	er common to Sec stake he found w	ctions 5 & vith this p	6 of T19	v, R14W, iffin's
Condition of the	accessories are as	follows: #1 Gone, #2	Gone, #3 Found Stu	mp, #4 Found Stu	ıb (10" dia	meter).	
			RAT	IFIED BY THE LAKE	ECO. PEER I	REVIEW G	ROUP
C. Description of monument f	for corner and accesso	ories established to perpo	etuate location the no	IN ACCORDA CH	IAIRMAN É	Σίχω.	
C-13 - Section corner co					=1. H,	4-48	
I set a $3/4$ " x 2^4 perpetuation of 1	4" re-bar with Lake the position of the	County Brass Cap insid original corner.	de of the 1" pipe,	and is accepted	as a caref	ul and fa	aithful
10" Cedar №17 ⁰ E 1	18.03' (60d spike in	W. side)				A-	Mar
11" Cedar N75 ⁰ W 3	30.04' (60d spike in	N.E. side)			S. S. S.	VIE OF	MCHC
7" maple (in clum 10" Beech N70 ⁰ E 7	mp) S21 ⁰ E 12.15' (60 76.96' (dock spike i	a spike in W. side) n N. side)			, <i>a</i>	··VUCNI	
` 		!	. 1	,	A	LAND	ELL
Signed by Kolut	I With	neel	Date <i>\</i>	14.98	- <u>*</u>	SURVEY(OR 🚶

24624