0FC 1 1000

SECTION

LAND CORNER RECORDATION CERTIFICATE RECORDED

FILING REQUIREMENT OF ACT 74, Mich. P.A. 1970

LAKE COUNTY, MI,

For corners in Lake		Lo	ocated in: Corner Code#				[PAGE AM 'S	0241 9			
1.	Public Land Survey		T 20N	R14W	M-11										
			T20N	R13W	A-11	Blecky, Myen					refero	ر			
			T	_ R			RECISTER OF DEEDS								
			T	R											
2.	Property Controlling	j s	Т	R											
	in Section	S	<u>T</u>	R		Registe	r of F	Joods	Ston	an 9 E	ila Ni	ımhar			
3.	Miscellaneous Property in Sec. Lot No Reco	s	<u>T</u>	R		registe	1 01 2	Jeeus	o Gtail	ip oc. r	He IV				
		,s	. <u>T</u>	<u>R</u>	····										
	Lot No Reco	rded Pla	t		· · · · · · · · · · · · · · · · · · · 	A 1 [В		EFG	HI	JK	LM			
			G		4000 4-	2	6	5	4	3	2	1			
her	Robert L. Wetherell, in a fi eby certify that under req	uirements	of P.A. 74, I	Michigan P.A.	of 1970, the corner	3 4	7	8	9	10	11	12			
	nts mentioned in lines 1 a es therefore as required ir					5 6	18	17	16	15	14	13			
Sta	tes Department of the Int	erior, Bure	au of Land	Management o	or by decree of a	7		_							
	urt of Law and/or that the conformance with the rule					8	19	20	21	22	23	24			
	a Court of Law; established					10	30	29	28	27	26	25			
recovered, found as expressed below:							-	20				-			
М.	11 - N.E. Cor. Sec. 36, T2	ON R14W.	- NW Cor	Sec 31 T20N	R13W Lake Co. Mi	12 13	31	32	33	34	35	36			
	Description of original														
	1887 - J. Mullet, G.L.O.				1916 - G.H. Johnson, Co. Sur.			1964 - R.A. Griffin, LS 13584 LC.R.C Liber 01, Page 263							
	#1 - 10" W. Pine S64°W 70 Links			1-¼" x 3" P	1-¼" x 3" Pipe										

#2 - 8" W. Pine N15°W 54 Links

<u> 1907 – J. Millard</u>

"Found 2.17 Chains South & 17 Links West of Established Corner: B.T's Agree" #3 - 12" Y. Pine Stump S81°W 1.64 Chains #4 – 12" Y. Pine Stump N30°E 72 Links Showed distance West of 2912.58' Showed distance North of 2721.18' Showed distance South 2673.00'

#5 - 12" B. Oak S25°W 30' #6 - 14" B. Oak N52°W 91'

1917 - G.H. Johnson, Co. Sur.

Measured 2853' North to 1/4 corner.

1949 - G. Blass, LS 5489

Found 1-1/4" Iron Pipe #7-24" B. Oak S24°E 44.1'

#8-24" B. Oak S34°W 49.3'

Found 1- 1/2" Pipe. Set 5" Square Conc. Mon.

#9 - P. Pole N79°E 69.80°

#10 - 7" R. Pine S39°E 112.40" #11 - 5" x 7' Cedar Post S45°E 46.7'

#12 - N.E. cor. Cabin Foundation S39°W 133.15`

#8 - 25" B. Oak S34°W 50.15'

#13 - 7" R. Pine N21°W 126.15"

1998 - R.L. Wetherell, LS 24624

U.S.F.S. Monument.

Unrecorded survey File No. 8650-98. Shows distance West to 1/4 corner of 2610.80'

B. Description of corner evidence found and/or method applied in restoring of reestablishing corner:

I found Griffin's 5" Square Concrete Monument 3 feet more or less North of roads East and West and 7 feet West of roads North and South. I measured 2610.80' West to 1/4 corner. I measured 2641.56 feet South to 1/4 corner. I measured 2953 feet more or less North to 1/4 corner.

Condition of the accessories are as follows: #1 Gone, #2 Gone, #3 Gone, #4 Gone, #5 Gone, #6 gone, #7 Gone, #8 Found in good condition, #9 Found in good condition, #10 Found in good condition, #11 Gone, #12 New Cabin #13 Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the 5" Square Concrete Monument as a substantial marker for the corner, and is accepted as a careful and faithful reestablishment of the RATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345
CHAIRMAN (2.3. ...)
DATE 10-19-99 position of the original corner. 07.03(4)

Northeast corner Cabin Foundation S48°W 118.81' 9" W. Oak (Clump of 4) N29°E 89.68' (60d spike in W. side) P. Pole N81°E 69.74' (Nail & cap in South side) #9

15" R. Pine S38°E 112.38' (dock spike in S.W. side) #10 11" R. Pine N20°W 126.16' (dock spike in S.W. side) #13

÷ }

6223