## SURVEY & REMONUMENTATION

OCT 2 9 1996

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE RECEIVED FOR RECORD

For the	Filing Requirem	ent of Act 74, Mich. P.A. 1970	96 SEP 30 PM 3: 19
For corners in  Lapeer (County)	Located In: Hadley	Corner Code #	70 021 0.9 (1) 9 7 9
(County)	inductor		Hallos in The Change
	T Car Do-	M-4	$\mathcal{O}$
Public Land Survey	T <u>6N</u> R <u>9E</u> T R	<u>M-4</u>	HSBIGTER OF BITEDS LARTER SERVICE TO HEAR
	T R		•
	T R		
Property Controlling     In Section	ST R ST R		port of the
3. Miscellaneous	s r R		
Property in Section	S R	Reg	ister of Deeds Stamp & File Number.
4 Lot No	Recorded Plat		
			A B C B E F G /H I J K L N
			3 1 3 3 2
			4 7 8 9 10 11 12
, Huston K. Kenned	Y, in a field survey onJUNE_3	, 19 96	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current			
manual of survey instruction	ns of the United States Department	of the Interior, Bureau of Land	7
Management or by a decree of above were in conformance	of a Court of Law and/or that the come e with the rules of the Michigan Board	r points mentioned in lines 3, 4 and Lof Professional Surveyors or by a	8 19 -20 -21 -22 -23 -24 -
Decree of a Court of Law; est	ablished, re-established, monumented	re-monumented, recovered, found	10 30 29 28 27 26 25
as expressed below:	orners, all in the same town and rai	uga may ha recorded	17-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-
on this certificate.	oniers, all ill the same town and rai	ige, may we recorded	12 31 32 33 34 35 36
A Description of origina	I monument and accessories and	or subsequent restoration:	13L
A. Description of original monument and accessories and/or subsequent restoration:  PEER GROUP  1817-GLO Carpenter, D.S.; Set Post; 14" Black Oak N51°E 12 Links; 13" Black Oak N59°W 19 Links  APPROVED LAND CORNER			
1.) 1974-Buckerfield, PS	5 #10868; LCRC L.2, Pg. 677 - Fnd	1/2" Iron Bar	PA 345 OF 1990
		1/2" Iron Rod, used same wit as 1 Iron Rod, used same wit as 1974 I	
4.) 1985-Harold N. Elrich, PS #18986; Survey L.6, Pg.972 - Fnd 1/2" Iron Rod, used same wit as 1974 LCRC /			
5.) 1987-Carlson, PS #91	189; Unrecorded Survey - Fnd 1/2"	Re-rod	RAY DAVIS PUS. CO. SURVEYS
			DATE 7-16-96
		·	
D. Desadaking of some	avidance found and/or mathod at	oplied in restoring or reestablishing	comer
•			
			e intersection of the existing centerline sting centerline of Richie Road extending
to the West, which	has a gravel surface. The West 1/	4 corner of Section 7, T6N, R10E, M	letamora Twp., $(\lambda-4)$ is located 72.25 feet
to the South, Found	d 1/2" Iron Rod w/fence-tree line	extending to the East.	
Witnesses from LCR	C #1 & Survey #5 were used to rec	over and verify the location of th	e found 1/2" Iron Rod.
I accepted the four	nd 1/2" Iron Rod as the best evid	ence of the original corner positi	on.
FIELD MEASUREMENTS	BETWEEN		
M-5 to M-4 GLO = 40	O chains or 2640.00 Ft.		•
H-4 to λ-4 72.25 F M-5 to N-4 2643.18			
	• •	stablished to perpetuate locating th	a position of the corner
<del>-</del>		•	stamped Lapeer County Remonumentation M-4
N45°W 54.17' Set PK	& Remon. Washer South face 10" 0		The state of the s
	& Remon. Washer NW face 14" Oak & Remon. Washer SW face 16" Oak		TE OF MICH
S57'W 77.54' Set PK	& Remon. Washer NW face 12" Oak		- HUSTON
South 72.25 Ft. four	nd 1/2" Iron Rod West 1/4 corner	of Section 7, T6N, R10E, Netamora	Twp., (A-4)
The selected location is	s accepted by me and is generally	y accepted by Professional Surveyo	rs as the lest available evadence of the
position of the original			17623
			Donath Comment
$( ) \Lambda$			TOPESSIONAL SAME
Signed by	4K4	Date J	uly 17, 1996
Surveyor's Michigan Licer	nse No. (17623		HIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Surveyor S michigan Licer	130 NO		REVISED MAY 14, 1975 REVISED JAN., 1983