SURVEY & REMONUMENTATION

JUL 2 9 1998

REHONUMENTATION

DECEIVED	ะกจ	PECORD
----------	-----	--------

S	EC	TI	OI	V

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

98 JUL 27 PM 3: 53

For corners in	and the second		
Lapeer Located in: Corner Code # County) Radky Repair Township	Heliesa De Vangh		
	LAPTER THE STATE OF THE STATE O		
1. Public Land Survey T			
TR			
2. Property Controlling S T R			
in Section S T R			
Property in Sec. S TR	Register of Deeds Stamp & File Number		
Decorded Plat	ARCDEFGHIJKL <u>M</u>		
4. Lot No, Recorded Plat	A B C D E F G H 1 J K L		
<u> </u>	2 6 5 4 3 2 1		
970 97	3 3 3 9 9 10 11 12		
Huston K. Kennedy in a field survey on 8/8, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in the current manual of survey instructions of the	4 - 7 - 8 - 9 - 10 - 11		
United States Department of the Interior, Bureau of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of by a decree of a count of Land Management of the Land Mana			
Board of Land Surveyors or by a Decree of a Court of Law, established, he-established, he-established,	8 19 20 21 22 23 24		
recovered, found as expressed below:	9		
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	10 30 29 28 27 26 25		
on this certificate.	11		
	12 31 32 33 34 35 36		
	13		
•			
B. Description of corner evidence found and/or method applied in restoring or reestablishing of 1997 Kennedy Surveying, Inc Kennedy, PS #17623 - Fnd 1/2" Iron Rod .40 below the extending to the East & West, which has a gravel surface, and in the existing of which has a gravel surface. Corner common to the Southeast corner of Section corner of Section 31, T7N, R10E, Lapeer Township (λ-13) is located 210.94 feet the as a common corner with the Northwest corner of Section 6, T6N, R10E, Metamor Witnesses from LCRC #1 were used to recover and verify the location of the formal corner of the section of the formal corner with the section of the formal corner of the section of the formal corner with the section of the formal corner of the section of the section of the formal corner of the section of the sec	venterline of Baldwin Road extending to the South 36, T7N, R9E, Elba Township (M-13) and Southwest to the East. This corner is being used and accepted a Township (A-1).		
I accepted the found 1/2" Iron Rod as the best evidence of the original corne			
Field Measurements see back side of LCRC			
and accessories established to perpetuate locating the	position of the corner:		
W-1 I replaced the found 1/2" Iron Rod with a 1/2" x 24" Iron Rod w/2" diameter br.	ass cap stamped Lapeer County Telenimentalion		
S27°W 64.12' Set PK & Remon Washer SE face 11" Elm S29°E 85.30' Set PK & Remon Washer West face 27" Oak S67°E 129.84' Set PK & Remon Washer West face Power Pole East 210.94 feet, Southeast corner Section 36, T7N, R10E, Elba Township (H-13)	PROFITSSIONAL PROFITS IN THE PROFITS		
The selected location is accepted by me and is generally accepted by Professional position of the original corner.	Surveyors as the best analyance Avidence of the		
Signed by	7-14-98		
Surveyor's Michigan License No. 176 Z.3			