SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

					NER RECORDATION CERTIFICAT hirement of Act 74, Mich. P.A. 197			
For	r corners in			mig nequ	mentene of Not 1-4, most that to			
	Lapeer		Located In: Elba Twp. Corner Code ##			94 NOV 30 AM 8: 31		
	(County)		COOdics			LIBER NO. 65 FAGE NO. 133		
1.	Public Land Survey		Τ	R 9E _ R _ R		Melione De Vings Register of Deeds LAPER COUNTY MICHIGAN		
				_ R	1	CALLER COURT IT PORTURE		
2.	Property Controlling		† †	_ R				
3.	Miscellaneous Property in Sec.	S	Ť Ť	_ R	R	Register of Deeds Stamp & File Number		
4.	Lot No,	Recorde	d Plat	·		ABCDEFGHIJKLN		
5.	Private Claims					2 6 5 3 2 1 -		
						3 4 7 8 9 9 10 11 12 12 12		
. 1	Huston K. Kenned	y inafi	eld survey	on	October 21 19 94	5		
to hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					6 18 17 16 15 15 13 13			
	current manual of survey instructions of the United States Department of the Interior, Bureau of Lam Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 the corner points mentioned in lines 3, 4 and 5 the law and the corner points are not of the law and law and the law and law and the law							
						6 19 20 27 22 23 24		
Court of Law; established, re-e			ished, mon	umented, r	e-monumented, recovered, found as	10		
	essed below: E: Not more than 4 corners, all in the same town and range, may be recorded				11			
	on this certificate					12 31 32 33 34 35 36		
Α.	Description of origina	l monume	ent and ac	cessories a	and/or subsequent restoration:			
	1817-GLO Wampler, D.S.; Set Post; 8" White Oak S43*W 47 Links; 13" Black Oak N87*W 73 L 1.) 1972-Renderson, P.S. #16043; LCRC L.002, Pg.65 - Fnd a Iron 2.) 1989-Meyer, P.S. #15406; Survey L.006, Pg.485 - Fnd a P.K. Nail					inks PEER GROUP APPROVED LAND CORNER PA 345 OF 1990 APPEER COUNTY		
						Must Com		
						RAY DAVIS P.S. CO. SURVEYOR		
						UA 14/1-2/-1		
					d applied in restoring or reestablishing			
	Baldwin Road, whi	ch has a	bituminous	surface t	o the North and South, and the center from Pod in a Monument Roy 102.75' to	Box in the intersection of the centerline of erline of Newark Road to the West, which the South in the centerline of Baldwin Road, id to the East, which is a bituminous surface.		
						the found $1/2^{\pi}$ Iron Rod in a Monument Box.		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the found 1/2" Iron Rod in a Monument Box as the best evidence of the original corner position.

M-9 I replaced the found 1/2" Iron Rod a 1/2" x 24" Iron Rod w/2" diameter brass cap stamped Lapeer County Remonumentation #17623 , H-9 in a existing Honument Box.

S40 E 69.15' Set PK & Remon. Washer SW face Power Pole S77 W 71.40' Set PK & Remon. Washer BW face 24" Oak N51 W 66.92' Set PK & Remon. Washer SW face 8" Elm S82 W 118.35' Set PK & Remon. Washer North face 21" Oak

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by Date November 1, 1994

Surveyor's Mightigan License No. 17623

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 21, 11

ACUSTOM MAY 14, 11