## BUHVEY & **HEMONUMENTATION**

APR 2 9 1996

REMONUMENTATION

RECEIVED FOR REGORD

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

95 SEP -7	PM 3: 07
i inco ku	лиовия. <u>27.3</u>
Melisen.	Da Haugh
peninten	OF FEEDS

10

12

<u>5</u> For corners in LAPEER Located In: Lapeer Corner Code ## LAPEER COUNTY ABOUT AN 10E 7N Public Land Survey \_ R R T \_\_\_\_ R \_ \_ R Τ\_ т \_\_\_ \_\_ R Property Controlling \_\_ T \_\_\_\_\_ R . in Section Miscellaneous S \_\_ T .\_\_\_\_ R \_ Register of Deeds Stamp & File Number Property in Sec. \_ , Recorded Plat \_ 4. Lot No. 5. Private Claims \_ 3 July Earl E. Gravlin 19th in a field survey on . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines, 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

History: Sibley 1824 Set Post Beech 8 S51W 20 Sugar 8 N36E 17 I-5 to J-5 78.86 I-5 to H-5 78.78, County Surveyor Sicklesteel 1905 Set stone, small stone S46E 60, Act 74 L2 P485 Henderson SE 39.3 PP, SE 36.1 Road Sign, NW 70.46 PP, Recorded Surveys Henderson L4 P697 N70W 70.8 PP, S60E 39.3 PP, S40E 46.1 Road Sign, L1 P333-335 Bates same as L4 P697, Gravlin L9 P 197 Found 1/2" Iron, S45E 39.9 Road Sign, N75W 71.3 PP, S75W 67.03 PP, I-5 to I-4 2652.19, I-5 to J-5 2586.4, Gravlin L8 P 465-466 same as L9 P 197, Kay L3 P987-989 Found 1/2" Iron S45E 39.9 Road Sign S43E 41.78 3" Steel Post, N75W 71.3 PP, S75W 67.03 PP, I-5 to H-5 2616.22, Elrich L9 P504-505 N75W 71.3 PP, S75W 67.03 PP, S45E 46.71 1/2" Iron #18986 I-5 to H-5 2616.22, Elrich L9 P764 Found 1/2" Iron, N70W 71.3 PP, S70W 67.03 PP, S70E 52.22 Road Sign, S80W 3.88 1/2" Iron, Henderson L2, P517 same as Act 74 I-5 to J-5 2586.86 I-5 to I-6 2656.27 Elrich L3 P262 same as Kay L3 P987-989, Elrich L7 P795 same as L9 P764, Gravlin L7 P673 Found PK Nail, N3OW 73.42 PP, S8OW 34.38 Nail top Fence Post, S5OE 56.35 TP, I-5 to H-5 2616.24, Gravlin L10 P840 same as L9 P504-505,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Gravlin L10 P517 same as L9 P764, Unrecorded Surveys Elrich 10/21/71 Job # 5625A, same as L4 P697. Subdivision Peppermill Acres. Road Commission, same as Kay, L3, P987-989 . Drain Commission Nothing.

Site Conditions: Found 1/2" Iron, Level Farmland, Asphalt Road North, South, East and West, Found 1/2" Iron Southwest 3.88. I5 to I4 2652.14 I5 to I6 2656.38 I5 to J5 2586.40 I5 to H5 2616.22

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

July 19th, 1995 FOUND 1/2" RE-ROD, SET BRASS CAP IN MON BOX N70°W 71.10' NAIL & TAG S SIDE POWER POLE S70°W 67.03' NAIL & TAG S SIDE POWER POLE S45 E 46.59' 1/2" RE-ROD CAP #18986 S80°W 3.88' 1/2" RE-ROD N20°E 91.29' NOTCH IN E END 18" CMP

PEER GROUP APPROVED LAND CORNER PA 345 OF 1990 APEER COUNTY

RAY DAVIS P.S. CO. SURVEYOR 7-13-95

Date

8-17-

Surveyor's Michigan License No.

Signed by \_

expressed below:

LIBER 3005 PAGE 0273

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983