SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

REMONUMENTATION

RECEIVED FOR RECORD

LAND	CORNER RECORDATION CERTIFICATE
Filing	Requirement of Act 74, Mich. P.A. 1970

94 NOV 18 PM 1: 48 LIBER NO. 0.6 1 NO. 200 10 7-

For corners in						nsie				(C. S	
LAPEER	Located In:	Corner Code ##			OF/ LAPER	PISTE	1 7 E	(3.93)	រ ខេត្តព	t	
County	OREGON TWP				LAPE	ign No. 1	•	• • •			
Public Land Survey	T <u>8N</u> R <u>9E</u> T R T R										
Property Controlling in Section Miscellaneous	S T R S T R S T R		Registe	er of D	eeds S	itamp	& File	e Nu	ımbe	er	•
Property in Sec.	S T R										_
4. Lot No	Recorded Plat			A B	C D	E F	G H	1	J K	12-	M -
do hereby certify that under re in lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance w Court of Law; established, expressed below:	in a field survey on quirements of P.A.74, Michigan P.A. of in conformance with regulations and ructions of the United States Departs fa Court of Law and/or that the corner inth the rules of the Michigan Board of re-established, monumented, re-m	of 1970, the corresponds in memoral of tules therefore as required in the ment of the Interior, Bureau of La r points mentioned in lines 3, 4 and I Land Surveyors or by a Decree of conumented, recovered, found	the fand 7 d 5 s	-1930	17 20	21-	22-		23-26-	13 24 25	
NOTE: Not more than 4 on this certificate	corners, all in the same town an e.	d range, may be recorded	12 13	_31	-32-	-33-	34	1	35—	-36	

Description of original monument and accessories and/or subsequent restoration:

1824 SYLVESTER SIBLEY D.S. SET 1/2 MILE POST WHITE OAK 32" N 31° W 34 LINKS, PINE 30" N 63° W 28 LINKS 1868 GILBERT BATES STAKE -PINE STUMP 30" S 72 1/2° W 55 LINKS, PINE 34" N 58½° W 115 LINKS
1972 ELRICH P.S. LAND CORNER RECORDATION CERTIFICATE LIBER 001, PAGES 185 & 186
N 30° W 47.65 FEET NAIL IN 10" MAPLE S 50° W 39.00 FEET 12" OAK
1975 HENDERSON P.S. LIBER 001, PAGE 532 FOUND P.K. NAIL (TIES MATCH 1972 LAND CORNER
RECORDATION CERTIFICATE)

1976 BATES P.S. LIBER 003, PAGE 576 FOUND P.K. NAIL (TIES MATCH PREVIOUS SURVEYS) .
1976 HENDERSON P.S. LIBER 003, PAGE 504 NO OBJECT STATED CORNER IS SOUTH 95.95 FEET FROM WEST 1/4 CORNER, SEC 18, T8N-R10E, MAYFIELD TWP (TIES MATCH PREVIOUS SURVEYS) (SEE BACK Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ELRICH P.S. FOUND 1/2" IRON RDD IN MONUMENT BOX 0.50 FEET EAST OF CENTERLINE OF MILLVILLE ROAD. FENCE AND TREE LINE RUNNING WEST OF FOUND CORNER. MEASURED NORTH 90.95 FEET TO WEST 1/4 CORNER OF SECTION 18, TBN-R10E, MAYFIELD TOWNSHIP. FOUND TWO WITNESSES FROM PREVIOUS SURVEYS THAT VERIFIED LOCATION OF FOUND 1/2" IRON ROD.

ACCEPTED FOUND 1/2" IRON ROAD IN MONUMENT BOX AS BEST LOCATION OF ORIGINAL POSITION OF EAST 1/4 CORNER OF SECTION 13, T8N-R9E, OREGON TOWNSHIP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6 SET STANDARD REMONUMENTATION CAP OVER FOUND 1/2" IRON ROAD

10" HICKORY N 30° E 71.48 FEET NAIL & WASHER 23" CHERRY N 80° W 57.85 FEET NAIL & WASHER NAIL & WASHER 28" MAPLE S 30° ₩ 58.04 FEET 5 70° W 38.74 FEET 20" OAK

Surveyor's Michigan License No. ___18986.

____ Date 710V

A (CONTINUED)

1980 BECK P.S. LIBER 005, PAGE 779 FOUND P.K. NAIL (TIES MATCH PREVIOUS SURVEY)

1983 ELRICH P.S. LIBER 006, PAGE 612 NO OBJECT STATED S 70° W 38.74 FEET P.K. IN 18" OAK N 88° W 31.29 FEET TELEPHONE POLE N 88° E 27.43 FEET TELEPHONE POLE N 30° W 47.46 FEET NAIL IN 12" MAPLE

1986 ELRICH P.S. LIBER 007, PAGE 340 ND OBJECT STATED (TIES MATCH 1972 LAND CORNER RECORDATION CERTIFICATE)

1986 ELRICH P.S. UNRECORDED FOUND P.K. NAIL (TIES SAME AS 1972 LAND CORNER RECORDATION CERTIFICATE)

1988 GRAVLIN P.S. LIBER 007, PAGE 996 & 997 NO OBJECT STATED (TIES MATCH 1972 LAND CORNER RECORDATION CERTIFICATE)

1988 ELRICH P.S LIEER 008, PAGE 054 FOUND P.K. NAIL
N 50° W 38.74 FEET 22" OAK, N 30° W 47.46 FEET 12" MAPLE,
N 68° W 31.29 FEET TELEPHONE POLE, WEST 32.95 FEET 1/2" IRON ROD

9858 08058 9777

 $EQC \subseteq \cdots$

9.00 MISC D REMLC P0075 REMONT 2.00