

MAY 2 8 1997

For corners in DEERFIELD TWP.

Property in Sec.

4. Lot No.

LAPEER

## 1996 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE

COMMISSION
------------

\_\_, Recorded Plat \_

Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

RECEIVE

RECORD

96 DEC 27 PH 1: 17

Meliosa De Vaugh
REGISTER OF DEEDS LAPFER TUNETY MODIFICAN

Register of Deeds Stamp & File Number

	(County)		
1.	Public Land Survey	T_09N_R_10E_	A-3
•	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	T R	
		T R	
		T R	
2.	Property Controlling	S	
	in Section	s T R	
3.	Miscellaneous	S T R	

Located In:

5. Private Claims \_\_ , in a field survey on \_ AUGUST FIELD

I, JONATHAN M. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

, /	ч в с	D 1	FG	H :	JΚ	Ł M
2	· 6	5	4 ·	3	2	1
3	7	8	Q	10	1:1	12
5 6	18	···17 ··	16	15	14	13
7 8	19	20	2]	22	- 23	24
9 10	30	29	28	27	- 26	25
11 12	31	32	33	34	35	36
1.3			<u> </u>	L	ļ	1

Description of original monument and accessories and/or subsequent restoration:

1834 GLO; BURNHAM , D.S.; SET POST; BEECH 14 S34E 34LKS., BEECH 7 N43E 9LKS.

1991 GRAVLIN, P.S.#23510; SURVEY L.009, PG.668; FND MONUMENT BOX; N45W 35.11' 8" APPLE, S40W 45.68' 24" ELM, S60E 34.11' 6" OAK

1991 GRAVLIN, P.S.#23510; SURVEY L.009, PG.926; FND MONUMENT BOX; SAME WITS AS 1991 SURVEY PEER GROUP ABOVE

**APPROVED LAND CORNER** PA 345 OF 1990 PER COUNTY

RAY DIWIS P.S. CO. SURVEYOR 8-27-96 DATE

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1996 ROWE ENG.; FIELD, P.S.#37276; FND. 1/2" ROD IN MONUMENT BOX 5' W. OF C/L WILLITS ROAD (GRAVEL TO N. ASPH. TO S.) & ON APPROX. C/L EXTENDED OF OTTER LAKE ROAD TO E. RECOVERED 2 REMAINING WITNESSES OF 1991 SURVEY CITED ABOVE INDICATING FND ROD IS IN SAME POSITION AS 1991 SURVEY

2651.24 A-3 TO A-2 2675.641 A-3 TO A-4

ACCEPTED FND. ROD AS BEST EVIDENCE OF ORIGINAL CORNER POSITION.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-3 SET STANDARD REMON CAP ON FND 1/2" ROD IN MON. BOX

N45°W, 35.21' FND. NAIL IN S. FACE 8" APPLE

56.83' P-K NAIL IN S. END 12" CMP N30°E,

45.64' FND. NAIL IN SE FACE 24" ELM S40°W.

70.74' P-K NAIL IN N. END 12" CMP S30°E,

49.29' NAIL W/TAG #37276 IN E. FACE 10" APPLE S35°W.

JONATHAN M. FIELD **PROFESSIONAL** SURVEYOR 37278 POFESSI

Signed by Surveyor's Michigan License No. 37276

\_\_\_\_ Date \_\_\_\_ 12-2-96

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197