## SURVEY & **TEMONUMENTATION**

APR 2 8 1995

COMMISSION

4. Lot No.

5. Private Claims

## 1994 REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

94 DEC 22 PH 2: 01 LIEER NO. 05 110 177 Meline Da brugh LAST TO STEEL OF STEELS

For corners in DEERFIELD LAPEER	TWP. Located In:	Corner Code #
(County)		
1. Public Land Survey	T_09N_R_10E_ TR TR	M-8
2. Property Controlling S in Section S Miscellaneous Property in Sec. S	T R T R T R T R	

Register of Deeds Stamp & File Number

\_, Recorded Plat \_

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

1 Δ 6 5 7 8 10 15 17 16 24 ( 20 19 26 10 29 28 27 30 11

BCDEFGHIJKLM

Description of original monument and accessories and/or subsequent restoration:

1822 GLO; WAMPLER, D.S.; SET 1/2 MILE POST; IRONWOOD 14 S2W 32LKS., IRONWOOD 7 N54W 17LKS.

1906 SICKLESTEEL, C.S.; STAKE 2 STONES; PINE 44 N54W 41 1/2LKS., PINE 40 S28W 57LKS.

NOTE ON SURVEY - E1/4 POST 19,9,11 NORTH 7 1/2

1972 HENDERSON-BATES; HENDERSON, P.S. #16043; SURVEY L.1, PG.758; SET 1/2" IRON ROD; N65°E

1972 HENDERSON-BATES; HENDERSON, P.S.#16043; SURVEI L.I, PG. (30; SEI 1/2" IRON ROD; NOS B 44.84' 6" OAR, N50°W 30.48' 6" MAPLE, S70°W 91.79' 10" ELM 1972 HENDERSON, P.S.#16043; LCRC L.1, PG.599; SET 1/2" IRON ROD IN GRAVEL ROAD INTERSECTION 1/2 WAY BETWEEN RIGHT OF WAY FENCES; SAME WITS AS 1972 SURVEY ABOVE 1976 RAY ENG.; RAY, P.S.#14096; SURVEY L.3, PG.982; FND 1/2" IRON ROD; SAME WITS AS 1972

1978 BECK-GRAVLIN; GRAVLIN, P.S.#23510; SURVEY L.4, PG.948; NO OBJECT STATED; NO WITS GIVEN

1984 GRAVLIN, P.S.#23510; SURVEY L.6, PG.749; FND 1/2" IRON; S45°E 41.27' T.POLE, N20°E 21.44'

8" OAK, N40°W 32.80' 10" MAPLE 1989 GRAVLIN, P.S.#23510; LCRC L.4, PG.255; FND 1/2" IRON; SAME WITS AS 1984 SURVEY ABOVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 ROWE ENG.; FIELD, P.S. #37276; FND 1/2" ROD (BENT & TWISTED) @ C/L - C/L GRAVEL ROADS

E-W-S RECOVERED 2 PREVIOUS WITNESSES INDICATING THAT FND ROD IS IN SAME POSITION AS 1972 HENDERSON-BATES SURVEY

2635.06' M-8 TO M-9 (MEAS. BY OTHERS) 2634.85' M-8 TO M-7 (MEAS. BY OTHERS)

ACCEPTED 1/2" ROD AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER POSITION LAPEER CO. PEER GROUP ACCEPTED 1/2" ROD AS ALSO BEING A-8 T9N-R11E

Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-8 REMOVED BENT ROD, SET 1/2" ROD W/ STANDARD BRASS CAP

N35°W, 32.56' SET NAIL W/ REMON TAG IN SW FACE 10" MAPLE

83.38' SET NAIL W/ REMON TAG IN N. FACE GUY POLE 567°₩,

41.31' SET NAIL W/ REMON TAG IN SW FACE CUT-OFF T. FOLE 541°E,

25.55' SET NAIL W/ REMON TAG IN NW FACE 10" OAK N21°E,

N65°E, 44.8' CENTER OF CLUSTER OF SMALL OAKS

91.5' ROTTED ELM STOMP 970°W,

PEER GROUP

APPROVED LAND CORNER

PA 345 OF 1990

DATE 12-22-94

LAPEE, P.COUNTY 201:CO History, A Yurayof Michigan License No. 37276

12-8-94

0 F M//

JONATHAN

M. FIELD

DURYEYOR

No. 37278

UBER 2005 PLEE 0177