1993

COMMISSION

5. Private Claims

expressed below:

REMONIMENTATION

PECELVED FOR RECORD

LAND CORNER RECO		:	CATE
Filing Requirement of	Act 74. N	lich. P.A.	1970

ATE 970	93 020 22	PM 3: 13
	LISTS NO. 22.	ZA NASAN
	LATTIC	
	,	
Regist	er of Deeds Stamo	& File Number

For corners in LAPEER Located In: Corner Code ## T 9N R 11E Public Land Survey _ R _ R 2. Property Controlling Ŧ R in Section __ T ___ 3. Miscellaneous ___ T ____ R _ Property in Sec. _ T ___

<u>Earl E. Gravlin</u>, in a field survey on _ October do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

M-11. Northeast corner Section 36

__ , Recorded Plat _

History: East and South and West town lines run by Joseph Wampler, 1821. Pages 445 and 447. Subdivision of township run by Hiram Burnham, second quarter, 1834. page 455. Witnesses Cedar 8 N5°W .15, Ash 12 S58°W .28 Set Post County Surveyors Record: Nothing in NE or SE 1/4. Recorded surveys: L002. P 201 Kay 1973

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site Conditions: Intersection Summers Road and Willis Road(both gravel) in cedar swamp(standing water)

Found 1/2" iron in place

Occupation: centerline road to west, north 26.6'(recorded .41 chains) centerline

road to east.(1/2" iron)

MEASUREMENT M-11 TO M-12 2628.97', M-11 TO M-10 2625.76'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 24, 1993

Surveyor's Michigan License No. .

Found 1/2" iron in place. Set brass cap

NORTH 26.60' 1/2" IRON A-11, T9N-R12E

880°W 51.55' FACE STOP SIGN POST

N40°E 69.35' NAIL & TAG E SIDE CORNER POST

N55°E 54.30 FACE STOP SIGN POST

OF MICHIG GRAVLIN rof. Surveyor Nο

Signed by _ 23510

APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983