1993

REMONUMENTATION

RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

93 DE	0.22	PH 3: 05	
IBER ta	5	_₩ ,	-

For corners in LAPEER Located In: Corner Code ## T 9N R 12E M-12_ 1. Public Land Survey T _____ R .__

___ T .____ R _

___ R _ ____ T ____ R _

Register of Deeds Stamp & File Number

BCDEFGH

Property in Sec.

_____, Recorded Plat _____

s _

5. Private Claims __

2. Property Controlling

Miscellaneous

in Section

I, Earl E. Gravlin , in a field survey on October do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

M-12. East quarter corner Section 36. East and South town lines run by Joseph Wampler, 1821. Pages 630 and 631. Subdivision of township run by Hiram Burnham, second quarter, 1834. page 638-640. Witnesses Beech 20 North .18 Do 16 S8.5 W .19 set post. County Surveyors Record: Book 2, page 96, Southwest quarter only Recorded survey L006 P 155 Kay

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Site conditions: Flat farmland Cade Road(gravel) north south, gravel road to east.

Found 5/8" iron in place. Occupation fence to west, centerline road to east. Appears to be common with W 1/4 corner 31-9-13.

MEASUREMENT M-12 TO M-13 2640.43 M-12 TO M-11 2640.45

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

October 19, 1993

Found 5/8" iron in place. Replaced with 1/2" iron and brass cap S82 $^\circ$ W 27.01 NAIL & TAG N SIDE GTE POLE

N40°W 101.51 NAIL & TAG NE SIDE POWER POLE N41°W 296.60' SE COR METAL BLDG. N25°W 350.09' SE COR HOUSE

NO9°W 243,77' NAIL & TAG E SIDE GTE POLE

OF MICHIG EARL E GRAVLIN Prof. Surveyor No. 23510 PROFESSIONA

Signed by _	<u> </u>	2 5	
Commence to A	ماه محمده المحمد المحمدة	33510	
Surveyor 5 N	Michigan License No.		

12/02/93